

Figure - 开发 Dev #113445

开发 Dev # 110122 (New): 【MK】 管理总票
开发 Dev # 110126 (New): 【MK】 【AF】 管理总票
开发 Dev # 110706 (New): 【MK】 【FW】 【GameMode】 【TC-RID: 1201-0204801】
【MK】 【FW】 【GameMode】 【TC-RID: 1201-0204803】 Game Mode GPU
2022-11-01 14:02 - CD FW-周聆洛

Status:	完成 Closed	Start date:	2022-11-01
Priority:	Normal	Due date:	
Assignee:	CD FW王武军	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
"把UE里面的第5章关于GPU（品质优先、最大分辨率、帧率、分辨率、抗锯齿） 完成 把需求文档中的4.1.4关于GPU完成 游戏模式设置： https://thundersoft.feishu.cn/file/boxcn4WSiuGyviHMRNOXhMSrEaf 游戏模式交互布局及流程图： https://thundersoft.feishu.cn/file/boxcnjVzEvgG4o3bvrp1A7yWChe 游戏模式需求文档： https://thundersoft.feishu.cn/docx/doxcnkCbTXyb4vXfjfbXetgwYxb			
Related issues:			
Related to Figure - Bug # 115172: 【AF】 【EVT2】 【游戏模式】 游戏模式GPU...			CLOSED 2023-01-09 2023-01-18

History

- #1 - 2022-11-01 14:11 - CD FW-周聆洛
- Subject changed from 【MK】 【FW】 【GameMode】 【TC-RID: 1201-0204801】 Game Mode GPU to 【MK】 【FW】 【GameMode】 【TC-RID: 1201-0204803】 Game Mode GPU
- #2 - 2022-11-07 10:47 - CD FW-周聆洛

游戏模式GPU配置接口
<https://thundersoft.feishu.cn/docx/V2UYdvFecoJGYhxWfAWcMfCDnsQ>
- #3 - 2022-11-11 18:13 - CD FW-周聆洛
- % Done changed from 0 to 90

完成90%，还有分辨率没有完成，需要BSP支持
- #4 - 2022-11-14 14:08 - CD FW-周聆洛
- Status changed from New to 进行中 In Progress
- #5 - 2022-11-14 14:09 - CD FW-周聆洛
- Status changed from 进行中 In Progress to 保留中 Pending
- #6 - 2022-11-14 14:43 - CD FW-周聆洛
- Assignee changed from CD FW-周聆洛 to CD FW王武军
- #7 - 2022-11-15 10:23 - CD FW王武军
- Status changed from 保留中 Pending to 进行中 In Progress

#8 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160962	general/platform/vendor/thundercom/apps/GameMode	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:GameMode:configure gpu prop when Game app launchconfigure sys.gamemode.statusTC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: I4efcf56cd56493f5ffc7870abc3d38fca41a5022			

#9 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160965	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:GameMode:force 2X/4X MSAA when entry game modeneed configure sys.gamemode.status 1need configure sys.egl.force_msa 2/4TC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: Ie69d4cc53875cf8422ae98fcf5ec9199cd00a4da			

#10 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161991	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lingluo.zhou@thundersoft.com
AF:Settings: Modify the fps list in GPU settingsModify the fps list in GPU settings.TC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: I0b648cd99100432a74819372f8e8abf7b07f04cf			

#11 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162035	general/platform/vendor/thundercom/apps/GameMode	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lingluo.zhou@thundersoft.com
AF:GameMode:ADD GPU SettingsADD GPU Settings.TC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: I39ec501c2b937718e6bbf5cc53e03c0e9fb35b75			

#12 - 2022-12-22 20:53 - CD FW-王伟**Gerrit Merge Information :**

ID	Project	Branch	Uploader
162521	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lingluo.zhou@thundersoft.com
AF:GameMode: Click the switch in settings, the database update field is incorrectTurn off the GPU switch in Settings, and the database does not save the correct value.TC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: I4facc4a42e0634d9369603ecc0e4b53c0ce6a03e			

#13 - 2022-12-27 20:06 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
172266	general/platform/build/soong	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:GameMode: Add packages allowed for adjust resolutionAdd com.android.server.thunderperf inpackage_allowed_list.txtTC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: Ife55965c743ece69dd84e021c17f1eccbe49d006			

#14 - 2022-12-27 20:06 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
172268	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:GameMode: Add service for adjust resolutionAdd service to GameMode use. And adjust resolution by PlatformCompat.TC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: I9916bb888ca2aaa7629f7078ed47503c9c65f31c			

#15 - 2022-12-27 20:06 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
172264	general/platform/vendor/thundercomm/apps/GameMode	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:GameMode: Adjust resolutionAdd logic to adjust resolution by PlatformCompat.TC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: I71e1221ac9907a993f1b9058eef4d3670419a9ac			

#16 - 2022-12-27 20:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172276	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:GameMode: Add SELinux sepolicy for Adjust resolutionAdd thunderperf_service SELinux sepolicyto adjust resolution by PlatformCompat.TC-RID: 1201-0204803IssueID: TS-R-DF-113445Change-Id: Ifd1c68e05eb484be05644ba8158738438633793e			

#17 - 2023-01-12 16:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
176168	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
BSP:LCD: Support dynamic frame rateSupport 30 45 frame rate dynamic modificationTC-RID: 1201-0100501IssueID: TS-R-DF-113445Change-Id: Ifac634988435a7145f38842b6a7612eaeabc0e91			

#18 - 2023-01-13 10:34 - CD FW王武军

■ 当前状态

目前游戏模式中对应的功能开发：品质设置、分辨率设置、帧率设置、抗锯齿设置
的基础功能已经全部完成，后续通过测试同事针对游戏模式功能的测试情况再继续应对具体功能的bug点。
该票现在关闭。

#19 - 2023-01-13 10:35 - CD FW王武军

- Status changed from 进行中 In Progress to 完成 Closed
- % Done changed from 90 to 100

#20 - 2023-10-07 17:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317320	general/platform/packages/apps/Settings	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:GameMode: In the VX1 model, the options for image quality and frame rate are hidden.TC-RID: 1201-0204803IssueID: TS-R-DF-113445, IOVDEV-42116Change-Id: I64dd8c4ddf26d6cc99efb41e3dcc99be056252bb			

#21 - 2023-10-12 22:12 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
319106	general/platform/packages/apps/Settings	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:GameMode: In the VX1 model, the options for image quality and frame rate are hidden.TC-RID: 1201-0204803IssueID: TS-R-DF-113445, IOVDEV-42116Change-Id: I64dd8c4ddf26d6cc99efb41e3dcc99be056252bb(cherry picked from commit 5b6de519b7d554f5834bdf83d43dc267e27da000)			