

Figure - Bug #113483

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT】【小窗模式】先打开一应用小窗，再打开另一个应用，进入多任务管理器，无小窗进程显示

2022-11-01 15:33 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-01
Priority:	Normal	Due date:	
Assignee:	DL FW-张挽强	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:	MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0042.X
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0053.X
Severity:	Major	Fixed Version:	2022-11-11
Reproducibility:	Every time	Root cause:	标志位判断有误，修改调用逻辑
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
2、后台无进程			
【测试步骤】			
1、打开图库小窗			
2、打开设置应用			
3、进入任务管理器查看后台进程卡片			
【预期结果】			
3、小窗卡片和设置进程卡片均有显示			
【实际结果】			
3、只有设置进程，没有小窗卡片			
Related issues:			
Related to Figure - Bug # 114243: 【AF】【EVT】【小窗模式】打开一个应用小窗...			
CLOSED 2022-12-01			

History

#1 - 2022-11-01 15:34 - CD TEST-方永红

- Description updated

#2 - 2022-11-02 14:31 - CDTS-TEST 周婷

- Severity changed from Normal to Major

#3 - 2022-11-07 20:11 - CDTS-TEST 周婷

- Target version changed from VX1_MCE_FSE_V3.0_update_20221115 to VX1_MCE_FSE_V4.0_20221128

请更新bug当前进展和依赖

#4 - 2022-11-10 16:49 - DL FW-张挽强

- Status changed from New to RESOLVED

- Assignee changed from DL FW-张挽强 to CD TEST-方永红

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-11-11
- Root cause set to 标志位判断有误，修改调用逻辑

#5 - 2022-11-14 11:26 - CD TEST-方永红

- File Phone-STS40X190122 2022-11-14 11-25-38.mp4 added
- Status changed from RESOLVED to VERIFY_FAILED
- Assignee changed from CD TEST- 方永红 to DL FW- 张挽强
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211120244

11.14

同上述操作步骤

可以同时出现小窗卡片和应用功能卡片

但是，小窗卡片无内容显示（黑屏）

验证失败

#6 - 2022-11-17 15:42 - CDTS-TEST 周婷

- Target version changed from VX1_MCE_FSE_V4.0_20221128 to MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)

#7 - 2022-12-01 16:49 - CD TEST-方永红

- Status changed from VERIFY_FAILED to VERIFIED
- Verified Version changed from FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211120244 to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0053.X101

12.1

根据上述测试步骤，可以同时出现小窗卡片和另一应用的进程卡片

关于黑屏问题，经协商，另起票跟踪

#8 - 2022-12-01 16:49 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#9 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161189	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	jian.hao@thundersoft.com
AF:MultiWindow:fullscreen app and freeform app enterRecent no freeform1.modify getdisplayfreeformtask return valueChange-Id: I2bb6464d2be21f67545a7848590a20d58a4ab1f3TC-RID: 1201-0204601IssueID: TS-R-BUG-113483			

Files			
Phone-STS40X190122 2022-11-01 15-27-33.mp4	12.3 MB	2022-11-01	CD TEST-方永红
1532.txt	4.4 MB	2022-11-01	CD TEST-方永红
Phone-STS40X190122 2022-11-14 11-25-38.mp4	29.2 MB	2022-11-14	CD TEST-方永红