

Figure - Bug #114106

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110873 (New): BSP-BVT测试-AUDIO

【AF】【EVT】【AUDIO】下拉消息框，会有短暂提示音

2022-11-23 11:45 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-23
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2022-12-09
Reproducibility:	Every time	Root cause:	更新通知音动作，非系统应用非白名单内的应用，
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、下拉消息框			
【预期结果】			
1、消息框出现，无声音提示			
【实际结果】			
1、下拉消息框，会有短暂提示音			
【复现率】			
5/5			

History

#1 - 2022-11-24 16:59 - CD MM陈海波

- Assignee changed from CD MM陈海波 to CD FW-王伟

此问题如之前讨论的, 下拉消息框，会有短暂提示音. 此短暂提示音需要删除.

10-31 19:00:15.892 5953 6150 I ExtendedNuUtils: printFileName fd(7) -> /product/media/audio/notifications/pixiedust.ogg

补充:

通过测试(11/16号版本), 似乎此问题已经得到了修复.

#2 - 2022-11-28 18:09 - CD FW 曹覃刚

- Category changed from AUDIO-FW to CD-FW

- Status changed from New to ASSIGNED

- Assignee changed from CD FW-王伟 to CD FW 曹覃刚

#3 - 2022-11-28 18:17 - CD MM陈海波

- File audio_after.txt added

不好意思, 此问题在11/28号的版本上还是存在.
验证方式:

- 1. 下拉消息框前, 执行命令:
adb shell dumpsys audio > audio_before.txt
- 2. 下拉消息框
- 3. 下拉消息框后, 执行命令:
adb shell dumpsys audio > audio_after.txt
- 4. 对比audio dumpsys 结果.
如附件(notification1.png和notification2.png)所示, 会有消息音发出来.

#4 - 2022-11-28 18:18 - CD MM陈海波

- File audio_before.txt added
- File notification.png added
- File notification2.png added

#5 - 2022-12-08 10:43 - CD FW 曹覃刚

- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖

#6 - 2022-12-08 10:45 - CD FW 曹覃刚

- Assignee changed from CD FW-程天颖 to CD FW 曹覃刚

#7 - 2022-12-08 18:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168621	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Adjust notification tone playback actionNon-system applications and Non-whitelisted applications will not play notification tonesTC-RID: 1201-0201902IssueID: TS-R-BUG-114106Change-Id: Ifc27fea1ce344a54738b5471db4bd624205348e3			

#8 - 2022-12-08 18:29 - CD FW 曹覃刚

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-09
- Root cause set to 更新通知音动作, 非系统应用非白名单内的应用, 不需要通知音, 下拉状态栏, 不需要通知音

提交已入库
<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+/168621>

#9 - 2022-12-09 10:18 - CD TEST-方永红

- Status changed from *RESOLVED* to *VERIFIED*
- Verified Version set to *FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212090644*

12.9
验证通过，下拉状态栏无提示音

#10 - 2022-12-09 10:18 - CD TEST-方永红
- Status changed from *VERIFIED* to *CLOSED*

Files				
audio_after.txt	14.2 KB	2022-11-28	CD MM陈海波	
audio_before.txt	13.4 KB	2022-11-28	CD MM陈海波	
notification.png	250 KB	2022-11-28	CD MM陈海波	
notification2.png	51.2 KB	2022-11-28	CD MM陈海波	