

Figure - Bug #114862

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111068 (New): AF-V3.0--Launcher/SystemUI-定制屏保

【AF】【EVT】【屏保】自定义屏保-本地图片，弹出授权框后选择不允许，重复两次，第三次点击添加后，弹框不出现，并且可以通过滚动看到其他屏保设置的内容

2022-12-27 15:31 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-27
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Major	Fixed Version:	2023-01-11
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开设置-屏保-自定义屏保			
2、点击本地图片添加按钮			
3、在弹出的提示框中选择不允许			
4、重复2、3			
5、再次点击本地图片添加按钮			
【预期结果】			
5、弹出授权框			
【实际结果】			
5、第三次点击添加后，弹框不出现			
并且可以通过滚动看到其他屏保设置的内容			

History

- #1 - 2022-12-27 17:20 - CD APP-王营
- Status changed from New to ASSIGNED
- #2 - 2022-12-28 10:02 - CD APP-王营
- Assignee changed from CD APP- 王营 to CD APP- 王宏
- #3 - 2023-01-03 16:31 - CD APP-王营
- Assignee changed from CD APP- 王宏 to CD APP- 王营
- #4 - 2023-01-03 16:38 - CD APP-王营

■ Current conclusion

为此应用预制读取照片权限。

■ My analysis

运行时权限用户拒绝2次后，系统将不会弹窗。

■ Next action
为此应用预制读取照片权限。

#5 - 2023-01-03 16:38 - CD APP-王营
- % Done changed from 0 to 30

#6 - 2023-01-10 09:51 - IoT scm
Gerrit Merge Information :

ID	Project	Branch	Uploader
175073	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com
FW: ScreenSaver: Add default permission for imagepicker1.Add default permission to remove the dialog.2.Permission is android.permission.WRITE_EXTERNAL_STORAGEETC-RID: 1201-0300604IssueID: TS-R-DF-114862Change-Id: Iaf8f9a46f0eb1a6d3cedc28702c675d0b4a05ca8			

#7 - 2023-01-10 09:52 - IoT scm
Gerrit Merge Information :

ID	Project	Branch	Uploader
175147	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com
FW: ScreenSaver: Add default permission for imagepicker1.Add default permission to remove the dialog.2.Permission is android.permission.WRITE_EXTERNAL_STORAGEETC-RID: 1201-0300604IssueID: TS-R-DF-114862Change-Id: I036f11eaec856d05772e5d5d6128e3103eb88d5			

#8 - 2023-01-10 10:13 - CD APP-王营
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王营to CD TEST-方永红
- % Done changed from 30 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-11
- Root cause set to 编码问题

■ Current conclusion
问题已解决，代码已经提交入库，可在01-11及以后的版本中验证此问题
■ My analysis
运行时权限用户拒绝2次后，系统将不会弹窗。
目前需要将读取相册权限预制，默认授予此权限后，不需要弹框提示授权。

页面识别鼠标滚轮问题，已经和需求沟通，不需要考虑鼠标操作场景，只适配用户手指点击和滑动。

■ Submit URL

<http://10.0.232.3:3307/gerrit/c/general/device/thundercomm/TCDEV/+/175147>
<http://10.0.232.3:3307/gerrit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+/175073>

#9 - 2023-01-11 10:24 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301110536

1.11
验证通过

#10 - 2023-01-11 10:25 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190122 2022-12-27 15-29-12.mp4	30.8 MB	2022-12-27	CD TEST-方永红