

Figure - Bug #114887

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】 【EVT】 【小窗模式】 从应用小窗跳转到设置的操作， 页面显示不全

2022-12-27 17:31 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-27
Priority:	High	Due date:	2023-02-10
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0062.X
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0069.X
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	当某个要启动的activity不支持freeform的时候,不要让
Test Type:	IT		
Description			
以时钟为例			
【前提条件】			
1、设备已开机			
2、时钟无通知权限			
【测试步骤】			
1、打开时钟小窗			
2、打开闹钟			
3、在时钟小窗下方弹出的提示中点击更改按钮			
【预期结果】			
3、跳到设置的相应页面（全屏）			
【实际结果】			
3、设置以小窗的形式打开， 页面显示不完整			

History

#1 - 2022-12-29 19:35 - DL FW-张挽强

- Assignee changed from DL FW-张挽强 to CD FW-鲁凯峰

#2 - 2023-01-11 21:18 - CD FW 曹覃刚

- Due date set to 2023-02-10

#3 - 2023-01-16 19:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
177068	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:MultiWindow: fix non resizeablewhen activity not support resizeable,don't start as freeform modeTC-RID: 1201-0204601IssueID: TS-R-BUG-114887Change-Id: I2f8e547ba72a6d06347967c37b2d3b193a865f22			

#4 - 2023-01-16 19:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
177067	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lukf0916@thundersoft.com
AF:Settings: fix no package install errorwhen goto NotificationSettings via onNewIntent, The intent dataisn't save, so used settings home page intent.TC-RID: 1201-0201803IssueID: TS-R-BUG-114887Change-Id: Ief5405be6664073ebd7e8122a266d2c122afb4c4			

#5 - 2023-01-17 09:58 - CD FW-鲁凯峰

- Status changed from New to RESOLVED
- Assignee changed from CD FW-鲁凯峰 to CD TEST-方永红
- Resolution changed from -- to FIXED
- Root cause set to 当某个要启动的activity不支持freeform的时候,不要设置成freeform模式

■ Current conclusion

问题已经解决

■ My analysis

当某个要启动的activity不支持freeform的时候,不要设置成freeform模式

■ Submit URL

<http://10.0.232.3:3307/gerrit/c/general/platform/frameworks/base/+177068>
<http://10.0.232.3:3307/gerrit/c/general/platform/packages/apps/Settings/+177067>

#6 - 2023-01-18 19:02 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- % Done changed from 0 to 100
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0069.X101

1.18

验证通过

#7 - 2023-01-18 19:03 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Phone-STs40X190122 2022-12-27 16-48-10.mp4	8.91 MB	2022-12-27	CD TEST-方永红
--	---------	------------	-------------