

Figure - Bug #114946

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114579 (New): GameMode

【AF】 【EVT】 【游戏模式】 工具箱中亮度调节到1%图标显示和控制中心的图标不一致

2022-12-29 18:08 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-29
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2022-12-30
Reproducibility:	Every time	Root cause:	亮度设置为最小时，图标展示未匹配。
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开游戏模式			
2、进入游戏界面			
3、调节工具箱亮度条亮度为1%			
4、打开控制中心，观察亮度图标显示			
【预期结果】			
2、工具箱中亮度调节到1%图标显示和控制中心的图标一致			
【实际结果】			
3、图标不一致			

History

#1 - 2022-12-30 17:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
173174	general/platform/vendor/thundercom m/apps/GameMode	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:GameMode:Modify brightness icon when it value is 1%.TC-RID: 1201-0204809IssueID: TS-R-BUG-114946Change-Id: If8aa5c7b0ea2d44d5e5fc40c56f020e67f8b82fd			

#2 - 2022-12-30 17:59 - CDFW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CDFW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No

- Fixed Version set to 2022-12-30
- Root cause set to 亮度设置为最小时，图标展示未匹配。

■ Current conclusion
已处理。

■ My analysis
亮度设置为最小时，图标展示未匹配导致。

■ Next action
测试验证。

#3 - 2023-01-06 11:06 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301060629

1.6
验证通过

#4 - 2023-01-06 11:06 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
1754.jpg	444 KB	2022-12-29	CD TEST-方永红