

Figure - Bug #115299

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting
【AF】【EVT】【蓝牙】设备蓝牙搜索 蓝牙手柄G50，其图标显示错误
2023-01-13 16:15 - 物联网测试组_CDTs 段小刚

Status:	CLOSED	Start date:	2023-01-13
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTs 段小刚	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0068.X
Need_Info:	TEST	Degrated:	No
Resolution:	WONTFIX	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	蓝牙手柄模式设置问题，无需处理。
Test Type:	IT		
Description			
【前提条件】			
1、设备打开蓝牙			
2、蓝牙手柄开启匹配模式			
【测试步骤】			
1、打开 蓝牙——与新设备进行配对			
2、查看搜索到的可连接设备			
【预期结果】			
2、搜索到蓝牙手柄，图标显示正确			
【实际结果】			
2、搜索到蓝牙手柄，图标显示为 键盘图标			
【复现率】			
2/2			

History

#1 - 2023-01-16 14:58 - CD FW-廖涛
- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to 物联网测试组_CDTs 段小刚
- % Done changed from 0 to 100
- Resolution changed from -- to WONTFIX
- Degrated changed from -- to No
- Root cause set to 蓝牙手柄模式设置问题，无需处理。

蓝牙手柄模式设置问题，无需处理。

#2 - 2023-01-16 15:01 - 物联网测试组_CDTs 段小刚
- File img_v2_45657fb5-57a2-409e-a032-633e528eb59g.jpg added
- Status changed from RESOLVED to VERIFIED

验证：其测试手柄有多种模式，之前没有调整到正确的手柄模式，导致出错的；手柄模式下，图标无误

#3 - 2023-01-16 15:01 - 物联网测试组_CDTS 段小刚
- Status changed from VERIFIED to CLOSED

问题解决，特此关闭

Files			
JjAHXQNjeR.jpg	9.21 KB	2023-01-13	物联网测试组_CDTS 段小刚
img_v2_45657fb5-57a2-409e-a032-633e528eb59g.jpg	29.2 KB	2023-01-16	物联网测试组_CDTS 段小刚