

Figure - Bug #115316

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting
【AF】【EVT】【设置】冷启动设置，会先闪过白屏
2023-01-14 16:18 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-14
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0068.X
Need_Info:	--	Degrated:	No
Resolution:	DUPLICATE	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2023-01-16
Reproducibility:	Every time	Root cause:	已在 #114566 票中处理
Test Type:	ST		
Description			
【前提条件】 1、设备已开机 2、后台无进程			
【测试步骤】 1、打开设			
【预期结果】 1、正常进入设置			
【实际结果】 1、冷启动设置，会先闪过白屏			

History

#1 - 2023-01-16 10:24 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD FW 曹覃刚

#2 - 2023-01-16 11:01 - CD FW 曹覃刚
- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to DUPLICATE
- Degrated changed from -- to No
- Fixed Version set to 2023-01-16
- Root cause set to 已在 #114566 票中处理

已在 #114566 票中处理，请使用最新版本检查

#3 - 2023-01-16 14:11 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301161238

1.16
验证通过

#4 - 2023-01-16 14:11 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#5 - 2023-01-17 17:59 - CD TEST-方永红
- Category set to CD-FW

Files			
Phone-TZ98765432 2023-01-14 16-17-48.mp4	6.75 MB	2023-01-14	CD TEST-方永红