

Figure - Bug #115613

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【通知中心】删除按钮、查看详情按钮、前往通知中心按钮，没有明显的press状态和disable状态

2023-01-31 17:16 - CD TEST-方永红

|                          |             |                   |                                                |
|--------------------------|-------------|-------------------|------------------------------------------------|
| Status:                  | CLOSED      | Start date:       | 2023-01-31                                     |
| Priority:                | Normal      | Due date:         |                                                |
| Assignee:                | CD TEST-方永红 | % Done:           | 100%                                           |
| Category:                | CD-FW       | Estimated time:   | 0.00 hour                                      |
| Target version:          |             | Found Version:    | FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0070.X |
| Need_Info:               | --          | Degrated:         | No                                             |
| Resolution:              | FIXED       | Verified Version: | FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X |
| Severity:                | Normal      | Fixed Version:    | 2023-02-02                                     |
| Reproducibility:         | Every time  | Root cause:       | UI调整                                           |
| Test Type:               | ST          |                   |                                                |
| Description              |             |                   |                                                |
| 【前提条件】                   |             |                   |                                                |
| 1、设备已开机                  |             |                   |                                                |
| 【测试步骤】                   |             |                   |                                                |
| 1、打开通知中心                 |             |                   |                                                |
| 2、点击删除按钮、查看详情按钮、前往通知中心按钮 |             |                   |                                                |
| 【预期结果】                   |             |                   |                                                |
| 2、上述按钮在点击时或长按时，均有明显的颜色变化 |             |                   |                                                |
| 【实际结果】                   |             |                   |                                                |
| 2、没有明显的press状态和disable状态 |             |                   |                                                |

History

#1 - 2023-02-01 20:39 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                             | Project                          | Branch                                    | Uploader                  |
|------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-------------------------------------------|---------------------------|
| 178729                                                                                                                                         | general/platform/frameworks/base | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | caoqg0702@thundersoft.com |
| AF:Notification: Add button press state effectTC-RID: 1201-0201902IssueID: TS-R-BUG-115613Change-Id: I865499a96f9bb3839395763a05d8f75057cf92d9 |                                  |                                           |                           |

#2 - 2023-02-01 20:41 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-02
- Root cause set to UI调整

#3 - 2023-02-02 10:57 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild\_HH\_VX1\_MCE\_FSE.M.R.user.01.00.0071.X101

2.2

验证通过

#4 - 2023-02-02 10:57 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

| Files    |         |            |             |
|----------|---------|------------|-------------|
| 1714.png | 67.8 KB | 2023-01-31 | CD TEST-方永红 |