

Figure - Bug #115700

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111051 (New): AF-V2.0-Launcher/SystemUI-通知中心

【AF】 【EVT】 【通知中心】 点击文字-隐藏通知，会直接跳转到设置页面

2023-02-01 16:22 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-01
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X
Severity:	Normal	Fixed Version:	2023-02-02
Reproducibility:	Every time	Root cause:	UI调整
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开通知中心			
2、展开隐藏通知			
3、点击文字-隐藏通知			
【预期结果】			
3、设备无反应			
【实际结果】			
3、会直接跳转到设置页面			

History

#1 - 2023-02-01 20:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
178740	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Disable click events for hidden notification labelsTC-RID: 1201-0201902IssueID: TS-R-BUG-115700Change-Id: I8d665b5fc13c40568aed59b197b4a17d34b799d4			

#2 - 2023-02-01 20:42 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-02

- Root cause set to UI调整

#3 - 2023-02-02 10:55 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X101

2.2
验证通过

#4 - 2023-02-02 10:57 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190078 2023-02-01 16-10-40.mp4	12.8 MB	2023-02-01	CD TEST-方永红