

Figure - Bug #115873

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114579 (New): GameMode

【AF】【EVT】【游戏模式】游戏模式setting中其二级功能设置没有对应右向图标

2023-02-03 18:21 - 物联网测试组_CDTS 段小刚

Status:	CLOSED	Start date:	2023-02-03
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 段小刚	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	TEST	Degrated:	--
Resolution:	DUPLICATE	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	Settings 中选项样式为全局，所以和 Bug #115786 是
Test Type:	IT		

Description
【前提条件】 1、设备已开机 【测试步骤】 1、查看设置-游戏模式设置 2、查看 防打扰设置和GPU设置栏后面 【预期结果】 2、与验收UI一致 【实际结果】 2、缺少 导向图标

History

#1 - 2023-02-03 18:24 - 物联网测试组_CDTS 段小刚
- File 0_20_Game Setting_1_3_防打扰设置.png added

备注三级导航里也应该有导向图标，详情见附图3

#2 - 2023-02-03 18:42 - CD FW-廖涛
- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to 物联网测试组_CDTS 段小刚
- Resolution changed from -- to DUPLICATE
- Root cause set to Settings 中选项样式为全局，所以和 Bug #115786 是一样的问题，重复 BUG。

■ Current conclusion
重复 BUG。

■ My analysis
Settings 中选项样式为全局，所以和 Bug #115786 是一样的问题，重复 BUG。

■ Next action

测试跟进。

#3 - 2023-02-06 10:34 - 物联网测试组_CDTS 段小刚

- Status changed from RESOLVED to VERIFIED

重复bug，已有对应bug再跟进

#4 - 2023-02-06 10:34 - 物联网测试组_CDTS 段小刚

- Status changed from VERIFIED to CLOSED

Files			
20230203-181649.jpg	121 KB	2023-02-03	物联网测试组_CDTS 段小刚
20230203-181747.jpg	204 KB	2023-02-03	物联网测试组_CDTS 段小刚
0_20_Game Setting_1_3_防打扰设置.png	670 KB	2023-02-03	物联网测试组_CDTS 段小刚