

Figure - Bug #116146

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】系统-语言和输入法-个人字典-中文-右上角添加，唤出键盘后点击左上角返回按钮，键盘仍停留在屏幕上不消失

2023-02-10 10:55 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-10
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0073.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X
Severity:	Normal	Fixed Version:	2023-02-10
Reproducibility:	Every time	Root cause:	Fragment 页面键盘管理问题。
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1.进入系统-语言和输入法-个人字典-中文页面			
2、点击右上角添加按钮			
3、唤出键盘后点击左上角返回按钮			
【预期结果】			
3、返回上一级页面，键盘收回			
【实际结果】			
3、返回上一级页面，键盘仍停留在屏幕上不消失			

History

#1 - 2023-02-10 18:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
180815	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix personal dictionary add page keyboard problem.TC-RID: 1201-0201809IssueID: TS-R-BUG-116146Change-Id: I511a7593bd848ed21deb98b556e1fea1ff07d7fa			

- #2 - 2023-02-10 19:03 - CD FW-廖涛
- Status changed from New to RESOLVED
 - Assignee changed from CD FW-廖涛 to CD TEST-方永红
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No

- Fixed Version set to 2023-02-10
- Root cause set to Fragment 页面键盘管理问题。

■ Current conclusion

已处理，代码已入库。

■ My analysis

Fragment 页面键盘管理问题。

■ Next action

测试验证。

#3 - 2023-02-14 18:20 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X101

2.14
验证通过

#4 - 2023-02-14 18:20 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190078 2023-02-10 10-55-15.mp4	7.19 MB	2023-02-10	CD TEST-方永红