

Figure - Bug #116446

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT3】【控制中心】快速向右滑动音量或亮度调节条至屏幕最右侧时，音量值或亮度值不能调节到100%

2023-02-22 14:27 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-22
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	TEST	Degrated:	--
Resolution:	WONTFIX	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	问题与115181相同，原生现象，不做修改
Test Type:	ST		

Description

【前提条件】

1、设备已开机

【测试步骤】

1、进入控制中心

2、手指在音量或亮度调节条上快速向右滑动至屏幕最右侧

【预期结果】

2、音量或亮度调节条上的值可以被调节到100%

【实际结果】

2、音量或亮度调节条上的值不能调节到100%

【日志】

见附件

History

- #1 - 2023-02-22 19:34 - CD FW 曹覃刚
- Status changed from New to NEED_INFO
 - Assignee changed from CD FW 曹覃刚 to CD Test赵飞
 - Need_Info changed from -- to TEST

Hi 飞哥

此票与下面这个票中的问题是一致的，请参考其中#16和#17的部分，感谢

<https://share.thundersoft.com/redmine/issues/115181>

- #2 - 2023-02-23 10:22 - CD Test赵飞
- Status changed from NEED_INFO to RESOLVED
 - % Done changed from 0 to 100
 - Resolution changed from -- to WONTFIX
 - Root cause set to 问题与115181相同，原生现象，不做修改

#3 - 2023-02-23 10:22 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

关闭此问题

#4 - 2023-02-23 10:22 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files				
logcat.txt	2.03 MB	2023-02-22	CD Test赵飞	
screen-20230222-012538.mp4	5.28 MB	2023-02-22	CD Test赵飞	