

Figure - Bug #116499

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI---Setting

【AF】【EVT3】【设置】关于本机 - 法律信息中，“壁纸”选项应该移除

2023-02-23 17:11 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-23
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-24
Reproducibility:	Every time	Root cause:	原生 AOSP 功能，未移除。
Test Type:	ST		

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】	
1、进入设置 - 关于本机 - 法律信息	
2、查看	
【预期结果】	
2、页面中无“壁纸”选项，与PRD保持一致	
【实际结果】	
2、页面中存在“壁纸”选项	
【日志】	
截图见附件	

History

#1 - 2023-02-24 13:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
183941	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settings: Set wallpaper attribution unavailable.TC-RID: 1201-0201810IssueID: TS-R-DF-116499Change-Id: I0d68708dfed90f220a13d9dbb1a1224ffaf2597f			

#2 - 2023-02-24 18:11 - CDFW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CDFW-廖涛 to CD Test赵飞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No

- Fixed Version set to 2023-02-24
- Root cause set to 原生 AOSP 功能, 未移除。

■ Current conclusion

已处理，代码已入库。

■ My analysis

壁纸入口已移除，在设置中还能搜索到，搜索中的选项会跟着 BUG(<https://share.thundersoft.com/redmine/issues/116503>) 统一处理，可以在 116503 下增加备注说明去除壁纸搜索。

■ Next action

测试验证。

#3 - 2023-02-27 13:46 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202302250116
验证结果：PASS

#4 - 2023-02-27 13:46 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files

Screenshot_20230223-170354.png	539 KB	2023-02-23	CD Test赵飞
--------------------------------	--------	------------	-----------