

Figure - Bug #116505

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting
【AF】【EVT】【设置】蓝牙配对的弹窗与UI设计不符
2023-02-23 17:48 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-23
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Resolution:	WONTFIX	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-02-23
Test Type:	ST	Root cause:	不属于 UI 问题，UI 已经和设计确认过。
Description			
【前提条件】 1、设备正常启动 【测试步骤】 1、进入设置 2、进行蓝牙配对 【预期结果】 2、配对弹框与UI设计一致 【实际结果】 2、配对弹框与UI设计一致 会出现弹窗并需要勾选访问通讯录和通话记录 【复现率】 3/3			

History

#1 - 2023-02-23 18:11 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to WONTFIX
- Degrated changed from -- to No
- Fixed Version set to 2023-02-23
- Root cause set to 不属于 UI 问题，UI 已经和设计确认过。

■ Current conclusion

无需修改，不是 UI 问题。

■ My analysis

不属于 UI 问题，UI 已经和设计确认过。

■ Next action

测试确认。

#2 - 2023-02-24 10:26 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#3 - 2023-02-24 10:26 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

17472.png	194 KB	2023-02-23	CD TEST-方永红
-----------	--------	------------	-------------