

Figure - Bug #116682

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111046 (New): AF-V2.0-系统手势

【AF】【EVT】【系统手势】后台有应用运行时,在桌面状态快速操作两次底部上滑,第二次上滑后再向底部滑动,会直接进入最近运行的应用中

2023-03-02 17:18 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-02
Priority:	Normal	Due date:	2023-03-17
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0079.C101
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Reproducibility:	Every time	Fixed Version:	2023-03-22
Test Type:	ST	Root cause:	AOSP问题
Description			
【前提条件】 1、设备正常启动 2、后台有应用 【测试步骤】 1.打开多个应用后台运行 2.返回桌面 3.操作两次底部上滑(第一次与第二次衔接稍快) 4.第二次操作上滑不松手并向下滑动 【预期结果】 4、第一次上划进入recent\第二次上划退出recent 【实际结果】 4、第二次上滑后再向底部滑动,会直接进入最近运行的应用中 【复现率】 3/3			

History

- #1 - 2023-03-03 15:23 - CDTS_TEST 王成
- Category changed from 客户jira bug to CD-FW
- #2 - 2023-03-03 15:26 - CD FW 曹覃刚
- Category changed from CD-FW to CD-APP
- Status changed from New to ASSIGNED
- #3 - 2023-03-03 16:54 - CD APP-王营
- Assignee changed from CD APP-王营 to CD APP-王宏
- #4 - 2023-03-07 11:13 - CD APP-王营
- Due date set to 2023-03-17

#5 - 2023-03-09 16:20 - CD APP-王宏

- % Done changed from 0 to 20

■ Current conclusion

分析中

■ My analysis

打印日志可知和OverviewInputConsumer相关，手势发生时和调用 mTarget.proxyTouchEvent(ev, mStartingInActivityBounds); 内部实现是mProxyTouchController.onControllerTouchEvent(ev)来处理的，但是 findControllerToHandleTouch(ev); 的对象发生改变， NoButtonQuickSwitchTouchController -> NavBarToHomeTouchController

■ Next action

继续调查根因

#6 - 2023-03-20 19:26 - CD APP-王宏

■ Current conclusion

分析中

■ My analysis

因为触发了界面更改，因此判断是和taskView相关的taskId启动Activity，因此根据相关方法打印堆栈，最终追踪到QuickstepLauncher\$onStateSetEnd\$QUICK_SWITCH_STATE_ORDINAL中，在此条件下，他去获取了RecentsView中的首个taskView,去完成启动。因此我注释掉了获取，直接调用getStateManager().goToState(NORMAL); 但是发现不可行，动画的执行会变的零散异常。

■ Next action

继续调查根因，还是从源头处阻止比较好

#7 - 2023-03-21 11:31 - CD APP-王宏

- % Done changed from 20 to 50

■ Current conclusion

已提交

■ My analysis

屏蔽掉此动画过程中的手势操作

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+188780>

#8 - 2023-03-21 16:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188780	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-1a1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Gesture:bug fixed1.Refuse gesture operation during the process of entering recentTC-RID: 0301-0205201IssueID: TS-R-BUG-116682Change-Id: 1a9407ff49ba6bebf3e2e008f7f40a57d339def7			

#9 - 2023-03-21 16:48 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-22
- Root cause set to AOSP问题

#10 - 2023-03-23 10:04 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101).202303220131

3.23

重复操作50次未复现

验证通过

#11 - 2023-03-23 10:04 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
20230302-171808.mp4	4.83 MB	2023-03-02	CD TEST-方永红