

Figure - Bug #116709

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】已连接的设备-连接偏好设置-蓝牙，点击开启蓝牙按钮，按钮响应缓慢

2023-03-03 17:14 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-03
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230303
Need_Info:	TEST	Degrated:	--
Resolution:	INVALID	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		

Description
【前提条件】 1、设备正常启动 【测试步骤】 1、进入设置-已连接的设备-连接偏好设置-蓝牙页面 2、点击蓝牙开关 【预期结果】 2、点击之后开关立即响应 【实际结果】 2、点击开启蓝牙按钮，按钮响应缓慢 【复现率】 3/3

History

- #1 - 2023-03-03 18:51 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD FW 曹覃刚
- #2 - 2023-03-06 11:25 - CD FW 曹覃刚
- Status changed from New to NEED_INFO
- Assignee changed from CD FW 曹覃刚到 CD TEST-方永红
- Need_Info changed from -- to TEST

Hi 永红

这个现象是正常的，蓝牙打开需要一段时间，UI也需要跟着同步响应
原生平板也是如此，请确认

- #3 - 2023-03-06 11:32 - CD TEST-方永红
- Status changed from NEED_INFO to RESOLVED
- Resolution changed from -- to INVALID

3.6
原生设计，不做处理

#4 - 2023-03-06 11:32 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#5 - 2023-03-06 11:33 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190078 2023-03-03 17-13-21.mp4	11.8 MB	2023-03-03	CD TEST-方永红