

Figure - Bug #116928

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111068 (New): AF-V3.0--Launcher/SystemUI-定制屏保

【AF】【EVT】【屏保】屏保-自定义屏保-选择相册，相册中有多张图片时，选择弹窗侧面无滚动条

2023-03-13 16:12 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-13
Priority:	Normal	Due date:	2023-03-17
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230317
Resolution:	FIXED	Degraded:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Reproducibility:	Every time	Fixed Version:	2023-03-17
Test Type:	ST	Root cause:	编码问题

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】	
1、进入设置-显示-屏保-自定义屏保	
2、选择相册	
3、滑动选择图片	
【预期结果】	
3、根据UI设计，选择弹窗右侧应该有滚动条	
【实际结果】	
3、选择弹窗侧面无滚动条	

History

#1 - 2023-03-16 16:15 - CD APP-王营

- Status changed from New to ASSIGNED

- % Done changed from 0 to 50

■ Current conclusion

问题已处理待验证

■ My analysis

图片列表RecyclerView宽度适配异常，滚动条被布局到dialog以外，需要调整RecyclerView的宽度布局方式。

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+/187778>

#2 - 2023-03-16 19:43 - CD APP-王营

- Due date set to 2023-03-17

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD APP-王营 to CD TEST-方永红

- % Done changed from 50 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No
- Fixed Version set to 2023-03-17
- Root cause set to 编码问题

#3 - 2023-03-20 16:54 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101).202303191230

3.20

验证通过

#4 - 2023-03-20 16:54 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1612.png	305 KB	2023-03-13	CD TEST-方永红