

Status:	CLOSED	Start date:	2023-03-20
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-20
Reproducibility:	Every time	Root cause:	AOSP 原生问题。
Test Type:	Free Test		
Description			
【测试步骤】 进入设置-通知-应用设置：已关闭切换到所有应用			
【预期结果】 列表显示已安装所有应用信息			
【测试结果】 未刷新显示所有应用， 仍显示已关闭应用信息			

History

#1 - 2023-03-20 19:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188627	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:Settings: Fix notification list filter problem.TC-RID: 1201-0201803IssueID: TS-R-BUG-117046Change-Id: I7d7aba22e64d0fd0147ce0a7406e6a7985ad7679

- #2 - 2023-03-20 19:03 - CD FW-廖涛
- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to 物联网测试组_CDTS 唐霞

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-03-20

- Root cause set to AOSP 原生问题。

■ Current conclusion

已处理， 代码已入库。

■ My analysis

AOSP 原生问题。 已关闭和所有应用的排序条件一样， 在进行切换时， 未做刷新处理。 新增筛选条件进行联合判断。

■ Next action

测试验证。

#3 - 2023-03-22 15:44 - 物联网测试组_CDTS 唐霞
- Status changed from *RESOLVED* to *VERIFIED*

验证通过，关闭问题单
验证版本：FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303220131

#4 - 2023-03-23 10:59 - CD TEST-方永红
- Status changed from *VERIFIED* to *CLOSED*