

Figure - Bug #117073

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【通知中心】【VC1&VX1】仅有隐藏通知时，展开通知，隐藏通知和通知中心标题中间空白过多

2023-03-21 17:52 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-21
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0084
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0088
Severity:	Normal	Fixed Version:	2023-03-23
Reproducibility:	Every time	Root cause:	UI高度调整
Test Type:	ST		
Description			
【测试步骤】			
1、模拟仅有隐藏通知的情况			
2、展开隐藏通知			
【预期结果】			
2、页面显示符合UI设计			
【实际结果】			
2、隐藏通知和通知中心标题中间空白过多			

History

#1 - 2023-03-22 19:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189077	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Adjust the height of the hidden notification block when it is expandedTC-RID: 1201-0201902IssueID: TS-R-BUG-117073Change-Id: Ia073b1a67fd62d76e9a888058d927a66eefcdaea			

#2 - 2023-03-22 19:21 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-23
- Root cause set to UI高度调整

#3 - 2023-04-04 10:05 - CD FW 曹覃刚

- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红

#4 - 2023-04-04 11:14 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0088.C102(X102)

4.4

验证通过

#5 - 2023-04-04 11:14 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
17493.png	288 KB	2023-03-21	CD TEST-方永红