

Figure - Bug #117084

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【通知中心】【VC1&VX1】划至通知中心底部，底部留白过多

2023-03-22 15:43 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-22
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	TEST	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Resolution:	INVALID	Degrated:	--
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】	
1、在通知中心有多余一屏的通知时，划动至通知中心底部	
【预期结果】	
1、页面显示同ui设计	
【实际结果】	
1、相比UI图，底部留白过多	

History

- #1 - 2023-03-22 17:46 - CD FW 曹覃刚
- Status changed from New to NEED_INFO
 - Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
 - Need_Info changed from -- to TEST

Hi 永红

如今天与产品沟通，这个现象是正常的，请确认

- #2 - 2023-03-22 18:56 - CD TEST-方永红
- Status changed from NEED_INFO to RESOLVED
 - Resolution changed from -- to INVALID
 - Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101).202303220131

3.22

确认为正常现象

- #3 - 2023-03-22 18:56 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#4 - 2023-03-22 18:56 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Snipaste_2023-03-22_15-34-57.png	414 KB	2023-03-22	CD TEST-方永红
----------------------------------	--------	------------	-------------