

Figure - Bug #117138

测试 Test-ST # 111337 (New): ST测试总票

测试 Test-ST # 116840 (New): 中控联调测试-AF

【AF】【EVT3】【音量调节】中控设置为静音，副屏断电再上电后，副屏音量显示非静音

2023-03-24 10:59 - CD Test赵飞

|                                                                                |             |                   |                                                |
|--------------------------------------------------------------------------------|-------------|-------------------|------------------------------------------------|
| Status:                                                                        | CLOSED      | Start date:       | 2023-03-24                                     |
| Priority:                                                                      | Normal      | Due date:         |                                                |
| Assignee:                                                                      | CD TEST-方永红 | % Done:           | 100%                                           |
| Category:                                                                      | AUDIO-FW    | Estimated time:   | 0.00 hour                                      |
| Target version:                                                                |             |                   |                                                |
| Need_Info:                                                                     | --          | Found Version:    | FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102) |
| Resolution:                                                                    | FIXED       | Degrated:         | No                                             |
| Severity:                                                                      | Normal      | Verified Version: | FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103) |
| Reproducibility:                                                               | Every time  | Fixed Version:    | 2023-04-18                                     |
| Test Type:                                                                     | ST          | Root cause:       | 中控和副屏音量同步优化                                    |
| Description                                                                    |             |                   |                                                |
| 【前提条件】<br>副屏与中控已连接                                                             |             |                   |                                                |
| 【测试步骤】<br>1、中控侧进入设置 - 声音<br>2、点击媒体音量的静音图标<br>3、副屏断电<br>4、副屏再上电启动<br>5、查看副屏音量显示 |             |                   |                                                |
| 【预期结果】<br>5、副屏音量显示仍然处于静音模式                                                     |             |                   |                                                |
| 【实际结果】<br>5、副屏音量显示非静音，但实际播放音乐时没有声音                                             |             |                   |                                                |

History

#1 - 2023-03-29 11:30 - Multimedia组-RD3\_TSCD 梁卿山  
- Status changed from New to ASSIGNED

Hi ALL,

根据当前的现象，发现该问题由于开机音量同步时没有向中控查询导致，需要增加接口。

#2 - 2023-04-04 17:32 - Multimedia组-RD3\_TSCD 梁卿山

Hi ALL ,  
■ 现状

当前接口已经增加，但中控端接口定义有问题，需要修改。  
副屏侧的对应已经完成，开发自测没有问题。

■ 下一步

等待中控修改接口。

#3 - 2023-04-11 13:53 - Multimedia组-RD3\_TSCD 梁卿山

- Assignee changed from Multimedia组-RD3\_TSCD 梁卿山 to CD Test赵飞

HI 赵飞

该问题当前提交可以修复，提交如下，开发本地自测ok。

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+191529>

请使用以下VB进行验证，中控版本请保持68以上，谢谢！

[http://192.168.87.26:8080/view/Projects/view/Project-IOT/job/VerifyBuild\\_for\\_IOT\\_6490/331/console](http://192.168.87.26:8080/view/Projects/view/Project-IOT/job/VerifyBuild_for_IOT_6490/331/console)

#4 - 2023-04-17 14:51 - CD TEST-方永红

- Assignee changed from CD Test赵飞 to Multimedia组-RD3\_TSCD 梁卿山

Hi,卿山

VB版本验证通过

【前提条件】

副屏与中控已连接

【测试步骤】

- 1、中控侧进入设置 - 声音
- 2、点击媒体音量的静音图标
- 3、副屏断电
- 4、副屏再上电启动
- 5、查看副屏音量显示

【测试结果】

- 5、副屏音量显示处于静音模式，实际播放音乐时没有声音

#5 - 2023-04-18 09:47 - Multimedia组-RD3\_TSCD 梁卿山

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from Multimedia组-RD3\_TSCD 梁卿山 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-04-18

- Root cause set to 中控和副屏音量同步优化

HI 永红

代码已经合入，请使用4/18后的版本进行验证，谢谢！

#6 - 2023-04-19 15:29 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild\_HH\_MCE\_FSE.M.D.user.01.00.C103(X103).202304190056

4.19

验证通过

#7 - 2023-04-19 15:29 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

| Files             |         |            |  |           |
|-------------------|---------|------------|--|-----------|
| 副屏音量状态（再次上电后）.png | 430 KB  | 2023-03-24 |  | CD Test赵飞 |
| 中控音量状态.jpg        | 127 KB  | 2023-03-24 |  | CD Test赵飞 |
| logcat.txt        | 5.75 MB | 2023-03-24 |  | CD Test赵飞 |