

Figure - Bug #117341

测试 Test-IT # 111062 (New): V3.0功能测试
测试 Test-IT # 111067 (New): AF-V3.0--Launcher/SystemUI-任务管理器

【AF】【EVT】【任务管理器】在有小窗的情况下，在recent中进行应用切换、再上划进入recent，有概率出现上划时进程卡片不随手势变小的情况（1/3）

2023-04-06 11:44 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-06
Priority:	Normal	Due date:	2023-04-20
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0089.C102(X103)
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Severity:	Normal	Fixed Version:	2023-04-12
Reproducibility:	Every time	Root cause:	AOSP问题
Test Type:	ST		
Description			
【测试步骤】 1、进入任务管理器 2、打开一个小窗应用 3、点击另一进程卡片 4、上划 5、重复步骤3-4（换个应用） 【预期结果】 5、每次上划应用卡片都随手势变小，且有蓝色选中框 【实际结果】 5、有概率出现上划时进程卡片不随手势变小的情况，此时也可成功进入任务管理器，但是该应用无蓝色选中框			

History

- #1 - 2023-04-06 13:35 - CD APP-王营
- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营 to CD APP-王宏
- #2 - 2023-04-07 11:26 - CD APP-王宏
- Fixed Version set to 2023-04-13
- 跟随 Bug #116969 之后再解决
- 在116969 验证包中未出现相关问题，故此延后到116969之后解决
- #3 - 2023-04-10 19:13 - CD APP-王营
- Due date set to 2023-04-20
- #4 - 2023-04-11 18:16 - CD APP-王宏
- % Done changed from 0 to 50

■ Current conclusion

已提交

■ My analysis

主要原因是获取运行时的task取到了小窗的，没有匹配上，所以，需要全屏应用缩小时，才没有任何反应。
故此在获取runningTask时候应该将小窗的给排除出去

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/193060>

#5 - 2023-04-11 19:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193060	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Gesture:Fixed the bug that the thumbnail does not shrink with the gestureTC-RID: 0301-0205201IssueID: TS-R-BUG-117341Change-Id: I167dbc9f34bc9bcfa49e2c68390e746aa0312cca			

#6 - 2023-04-11 19:36 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Fixed Version changed from 2023-04-13 to 2023-04-12
- Root cause set to AOSP问题

#7 - 2023-04-12 10:18 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103).202304120453

4.12

验证通过

#8 - 2023-04-12 10:18 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Phone-1A2212290000001651 2023-04-06 11-43-53.mp4	11.2 MB	2023-04-06	CD TEST-方永红
--	---------	------------	-------------