

Figure - Bug #117351

测试 Test-ST # 111337 (New): ST测试总票

测试 Test-ST # 116840 (New): 中控联调测试-AF

【AF】【EVT3】【设置】在设置页面通过中控遥控器向下进行选择时，预选栏会从右侧直接跳到左侧区域

2023-04-06 19:49 - CD Test赵飞

Status:	CLOSED	Start date:	2023-04-06
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0089
Need_Info:	TEST	Degrated:	--
Resolution:	WONTFIX	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	AOSP 原生行为。
Test Type:	ST		

Description	
【前提条件】	
1、副屏连接中控	
【测试步骤】	
1、副屏打开设置	
2、中控侧打开遥控器	
3、通过遥控器把预选栏调整到设置页面右侧区域	
4、中控侧连续在遥控器中按“下”	
【预期结果】	
4、预选栏会一直向下，直到选中最后一项	
【实际结果】	
4、预选栏会一直向下，然后跳到了左侧区域	

History

#1 - 2023-04-07 11:09 - CD FW-廖涛

- Status changed from New to NEED_INFO
- Assignee changed from CD FW-廖涛 to CD Test赵飞
- Need_Info changed from -- to TEST
- Root cause set to AOSP 原生行为。

My analysis

根据分析，在右侧定位到底部时，若左侧还未到底部，再往下，会定位到左侧的下一个选项；当左侧已经到底部，右侧定位到底部再往下时，不会再定位到左侧；这个是系统行为，不需要处理。

Next action

测试确认。

#2 - 2023-04-12 10:53 - CDTs_TEST 王成

- Category changed from CD-FW to 依赖客户及其供应商解决
- Assignee changed from CD Test赵飞 to CD TEST-方永红

与客户同步下，系统原生机制，不解决

#3 - 2023-04-14 17:54 - CD TEST-方永红
- Status changed from NEED_INFO to RESOLVED
- Resolution changed from -- to WONTFIX

4.14
确认为原生机制

#4 - 2023-04-14 17:54 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#5 - 2023-04-14 17:54 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files				
副屏.log.txt	2.71 MB	2023-04-06	CD Test赵飞	
20230406-194831.mp4	10.1 MB	2023-04-06	CD Test赵飞	