

Figure - Bug #117437

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT3】【小窗模式】豌豆荚下载应用之后，无法安装，应用在小窗和全屏之间来回切换

2023-04-13 14:43 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-13
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0091.C103(X103)
Resolution:	FIXED	Degraded:	--
Severity:	Major	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	Settings Crash导致的界面无法调整
Description			
【测试步骤】			
1.使用豌豆荚安装应用			
【预期结果】			
1、弹出相应弹窗并成功安装			
【实际结果】			
1、无法安装，应用在小窗和全屏之间来回切换，出现各种异常显示			

History

#1 - 2023-04-13 14:47 - CD TEST-方永红
- File Phone-STS40X190078 2023-04-13 14-37-53.zip added

#2 - 2023-04-15 19:52 - CD FW-鲁凯峰

和packageInstaller冲突了,目前还在想办法解决

#3 - 2023-04-19 19:58 - CD FW 曹覃刚
- Status changed from New to ASSIGNED

当前状况
今日owner请假，暂无进展，明天开始更新

下一步计划
继续解析

#4 - 2023-04-20 20:30 - CD FW-鲁凯峰
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-鲁凯峰 to CD TEST-方永红
- Resolution changed from -- to FIXED
- Root cause set to Settings Crash导致的界面无法调整

■ Current conclusion

问题已经解决

■ My analysis

Settings Crash导致的界面无法调整

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+194857>

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+194967>

#5 - 2023-04-21 10:30 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- % Done changed from 0 to 100
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103).202304210449

4.21

验证通过

#6 - 2023-04-21 10:30 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

4131437.txt	4.08 MB	2023-04-13	CD TEST-方永红
Phone-STS40X190078 2023-04-13 14-37-53.zip	17.8 MB	2023-04-13	CD TEST-方永红