

Figure - Bug #117494

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111067 (New): AF-V3.0--Launcher/SystemUI-任务管理器

【AF】【EVT】【任务管理器】左手模式下打开小窗应用，进入recent,进程卡片无法补齐

2023-04-14 14:48 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-14
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Resolution:	FIXED	Degrated:	--
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Reproducibility:	Every time	Fixed Version:	2023-04-21
Test Type:	ST	Root cause:	编码问题
Description			
【前置条件】 后台有应用进程			
【测试步骤】 1.recent中打开音乐小窗 2、进入recent			
【预期结果】 2、小窗卡片出现在正确的位置，空白卡片自动补齐			
【实际结果】 2、进程卡片无法补齐			
Related issues:			
Related to Figure - Bug # 117532: 【AF】【EVT】【任务管理器】概率出现，后台...			CLOSED 2023-04-17

History

#1 - 2023-04-14 18:24 - CD APP-王营

- Status changed from New to ASSIGNED

#2 - 2023-04-19 14:24 - CD APP-王宏

- File bugreport-figure_CN-SKQ1.220201.001-2023-04-11-11-56-33.zip added

复现一次

#3 - 2023-04-19 16:14 - CD APP-王宏

【复现步骤】

- 1.清空recent,返回桌面
- 2、打开一个小窗
- 3.打开一个全屏应用
- 4.进入recnet
- 5.反复操作

#4 - 2023-04-19 19:59 - CD APP-王宏

- % Done changed from 0 to 20

■ Current conclusion

分析中

■ My analysis

目前已知是自定义控件中的滚动范围变化导致bug产生，child数目是够的，但是没有展示在对的位置

■ Next action

继续跟踪排查，找出bug产生的原因

#5 - 2023-04-20 17:38 - CD APP-王宏

- % Done changed from 20 to 50

■ Current conclusion

已提交

■ My analysis

根据分析是

protected boolean getPageScrolls(int[] outPageScrolls, boolean layoutChildren, ComputePageScrollsLogic scrollLogic)
scrollLogic中的逻辑返回了false,导致没有获取到正确的PageScroll，
导致绘制的View 出现在了别的位置，比如重叠，比如屏幕之外，
解决方案是在进入recent之前的showRunningTask中注释掉不必需要的addView(),layout()
■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/194980>

#6 - 2023-04-20 19:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194980	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:taskView display exception1.issue 117494 The recent card cannot be completed2.issue 117532 Background running programs show overlappingTC-RID: 0301-0205302IssueID: TS-R-BUG-117494Change-Id: I56abb57e13dadd98296fd6724f441e06f5ab4ab			

#7 - 2023-04-20 19:25 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-04-21
- Root cause set to 编码问题

#8 - 2023-04-21 13:54 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103).202304210449

4.21
验证通过

- #9 - 2023-04-21 13:54 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190078 2023-04-14 14-34-00.mp4	9.5 MB	2023-04-14	CD TEST-方永红
4141433.txt	5.63 MB	2023-04-14	CD TEST-方永红
bugreport-figure_CN-SKQ1.220201.001-2023-04-11-11-56-33.zip	6.52 MB	2023-04-19	CD APP-王宏