

Figure - Bug #117504

【IOVISSUE-4236】【EET】【VC1】【PPV】【副屏】【实车013】当副屏打开第三方应用时，APP显示比例不
适配

2023-04-14 15:40 - 物联网测试组_TSCD 王维

Status:	CLOSED	Start date:	2023-04-14
Priority:	Normal	Due date:	
Assignee:	物联网测试组_TSCD 王维	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:		Found Version:	中控版本：03.02.0068.C101副屏版本：0086
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	已确认为第三方应用问题
Test Type:	ST		

Description

【测试者】陈磊锋

【车辆VIN】LJD8AB3F3N0015013

【问题时间】2023.4.13

【车辆环境】EE

【前提条件】1、亮屏待机下，无应用运行

2、多媒体功能正常

【操作步骤】

1、设置在副屏任意打开一第三方应用，查看显示

【期望结果】第三方应用显示比例与副屏适配

【实际结果】第三方应用显示比例与副屏不适配

【复归方法】无

【复现率】5/5

【备注】副屏版本 0086

【需求依据】<https://ofs.human-horizons.com/#/download/index/OtE0CObl6UE%3D>

【LOG】无

History

- #1 - 2023-04-14 15:54 - CD FW 曹覃刚
- Category changed from CD-FW to 依赖客户及其供应商解决
 - Status changed from New to NEED_INFO
 - Assignee changed from CD FW 曹覃刚 to 物联网测试组_TSCD 王维

Hi 王维

这个属于三方应用的适配问题，取决于应用自身
请帮助同步此信息，谢谢

- #2 - 2023-04-17 15:44 - 物联网测试组_TSCD 王维
- Status changed from NEED_INFO to RESOLVED
 - Root cause set to 已确认为第三方应用问题

- #3 - 2023-04-17 15:49 - 物联网测试组_TSCD 王维
- Status changed from RESOLVED to VERIFIED

#4 - 2023-04-17 15:50 - 物联网测试组_TSCD 王维
- Status changed from VERIFIED to CLOSED