

Figure - Bug #117531

测试 Test-IT # 111062 (New): V3.0功能测试
测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口
【AF】【EVT】【小窗模式】低概率出现，小窗模式下点击进入全屏模式设备重启
2023-04-17 15:54 - 物联网测试组_CDTS 唐霞

Status:	CLOSED	Start date:	2023-04-17
Priority:	High	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	0%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Need_Info:	--	Degrated:	--
Resolution:	DUPLICATE	Verified Version:	
Severity:	Critical	Fixed Version:	
Reproducibility:	Rarely	Root cause:	跟#117475相同
Test Type:	Release Test		
Description			
【测试步骤】 QQ音乐mini小窗模式下点击进入小窗模式，再点击导航栏全屏按钮 【预期结果】 进入全凭模式 【测试结果】 设备重启 备注：图库在全屏模式下点击进入全屏设备重启（出现1次）			

History

- #1 - 2023-04-17 19:51 - CD FW-鲁凯峰
- Status changed from New to RESOLVED
- Assignee changed from CD FW- 鲁凯峰 to 物联网测试组_CDTS 唐霞
- Resolution changed from -- to DUPLICATE
- Root cause set to 跟#117475相同

从日志log看 和 #117475 是相同的问题，请在#117475 上跟踪

```
04-17 14:19:25.081 3569 3569 F DEBUG : Cmdline: system_server
04-17 14:19:25.081 3569 3569 F DEBUG : pid: 1559, tid: 1622, name: android.anim >>> system_server <<<
04-17 14:19:25.081 3569 3569 F DEBUG : uid: 1000
04-17 14:19:25.081 3569 3569 F DEBUG : signal 11 (SIGSEGV), code 1 (SEGV_MAPERR), fault addr 0x0
04-17 14:19:25.081 3569 3569 F DEBUG : Cause: null pointer dereference
04-17 14:19:25.081 3569 3569 F DEBUG : x0 b4000075a23f5d90 x1 b4000075d2448098 x2 b400007542534918 x3 b4000074f2421c50
04-17 14:19:25.081 3569 3569 F DEBUG : x4 0000000000000000 x5 0000000000000004 x6 000000006fa7cf58 x7 00000000c2ee0000
04-17 14:19:25.081 3569 3569 F DEBUG : x8 0000000000000000 x9 ffffffff x10 0000000000000000 x11 0000000000000000
04-17 14:19:25.081 3569 3569 F DEBUG : x12 0000ffff000000eff x13 00000000f6c00bf7 x14 000000001304ac90 x15 00000000702b88c8
04-17 14:19:25.081 3569 3569 F DEBUG : x16 00000077e49f9278 x17 00000077fd216ec0 x18 000000743a476000 x19 0000000000000000
04-17 14:19:25.081 3569 3569 F DEBUG : x20 b4000075d2448098 x21 b4000075a23f5d90 x22 0000000000000000 x23 0000000000000000
04-17 14:19:25.081 3569 3569 F DEBUG : x24 000000743ad8c000 x25 0000000000000000 x26 000000743ad8b338 x27 0000000000000000
04-17 14:19:25.081 3569 3569 F DEBUG : x28 0000000099425d90 x29 000000743ad8b290
04-17 14:19:25.081 3569 3569 F DEBUG : lr 00000077e496d9a8 sp 000000743ad8b290 pc 00000077fd216ee0 pst 0000000060001000
04-17 14:19:25.081 3569 3569 F DEBUG : backtrace:
04-17 14:19:25.081 3569 3569 F DEBUG : #00 pc 0000000000000000 /system/lib64/libutils.so (android::RefBase::decStrong(void const*) const+32) (BuildId:
```

b940f836006eead456c936e97e64d2d4)
04-17 14:19:25.081 3569 3569 F DEBUG : #01 pc 000000000009e9a4 /system/lib64/libgui.so (android::layer_state_t::~~layer_state_t()+280) (BuildId: 981246754542aed59a356fd4b365d03b)
04-17 14:19:25.081 3569 3569 F DEBUG : #02 pc 00000000000f1048 /system/lib64/libgui.so (android::SurfaceComposerClient::Transaction::clear()+304) (BuildId:

#2 - 2023-04-17 20:18 - CD TEST-方永红

同117475
先关闭此bug

#3 - 2023-04-17 20:19 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#4 - 2023-04-17 20:19 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
417.7z	19.1 MB	2023-04-17	物联网测试组_CDTS 唐霞
tlog_sts40x190067_000123_0417142424.tar.gz	33.6 MB	2023-04-17	物联网测试组_CDTS 唐霞