

Status:	完成 Closed	Start date:	2023-04-28
Priority:	Normal	Due date:	
Assignee:	CD BSP-杜磊	% Done:	80%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
在上电开机时显示第一帧图片			
Subtasks:			
需求 Requirement # 117723: [【DVT1】【OTA】OTA 更新UEFI阶段显示图片到spunvm 分区			New

History

- #1 - 2023-04-25 19:36 - CD BSP-杜磊
- Subject changed from [【DVT1】【Display】] to [【DVT1】【Display】开机图片显示]
 - Description updated
 - Category set to BSP
 - Assignee set to CD BSP-杜磊

#2 - 2023-04-28 13:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196848	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shuang.li_a@thundersoft.com
BSP:Security:Skip the boot prompt in UNlocked stateComment out the prompted stringTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: I33e05c9a422b86dd627f066cb369124fe566c9b1			

#3 - 2023-04-28 18:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197087	general/platform/vendor/thundercomm/spunvm_postinstall	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yepeng0322@thundersoft.com
BSP:Display: Add custom logo to spunvm partition[4/5]Add custom logo spunvm image to vendor for postinstallVC1 and VX1 use same on logoTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: I6b390f561aa341409f3cd42953d1469b811b111a			

#4 - 2023-04-28 18:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

197012	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	yepeng0322@thundersoft.com
BSP:Display: Add custom logo to spunvm partition[5/5]Add the costom logo partition for postinstallTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Ic99e2a47f9eac4b2146ccf26a2fd0f79995df3f3			

#5 - 2023-04-28 18:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196093	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	dulei0503@thundersoft.com
BSP:Display: Bringup VC1 lcd in uefi[1/4]1. lint max96755g ic and turn on backlight2. Add vc1 panel param to uefiTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Ic9e5be59ee9b1ebdfe08123b12cd5fb86afe8562			

#6 - 2023-04-28 18:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196374	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	dulei0503@thundersoft.com
BSP:Display: Add custom logo to spunvm partition[2/5]Save custom logo to spunvm partitionLoad and display the custom logo in XBLTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: I635a131e98978d1df574296a7eb8b52bcad95c0f			

#7 - 2023-04-28 18:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196625	general/boot_images	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	dulei0503@thundersoft.com
BSP:Display: Bringup VX1 lcd in uefi[1/2]1. Add new vx1 lcd panel params2. Set max96755x init code for vx13. Both VC1 and VX1 lcd compatibleTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: I55ba62b4cbc6e9ef3464517c8256a0f6012cf13f			

Gerrit Merge Information :

ID	Project	Branch	Uploader
196379	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:Display: Bringup VC1 lcd in uefi[4/4]Fix display drm error in kernel space.[sde error]unable to find appropriate mixersTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: If258b79c37c8a02691df525fd242010f8e0fd4c1			

Gerrit Merge Information :

ID	Project	Branch	Uploader
196323	general/aop_proc	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:Display: Bringup VC1 lcd in uefi[2/3]Set pm8009 ldo1 on for max96755gTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Idbc7245cd99ee3ff899b0d3c8e818237553d5e3f			

Gerrit Merge Information :

ID	Project	Branch	Uploader
196327	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:Display: Bringup VC1 lcd in uefi[3/4]Enable vc1 lcd backlight to 50%TC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: I9b55b68f5bebdbdf7e082dcde6f6ebe10f77a655			

Gerrit Merge Information :

ID	Project	Branch	Uploader
196373	general/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:Display: Add custom logo to spunvm partition[1/5]Add the costum logo partition in content.xmlIf the logo size larger than 1M, need save logoto large partionTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Id2abe48de585ca67704a59de53051a19088ca66a			

#12 - 2023-04-28 18:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196376	general/turbox/tools/build_script/dev ice	Pre_figure_turbox-c2130c-la1.1-vend o-r-dev	dulei0503@thundersoft.com
BSP:Display: Add custom logo to spunvm partition[3/5]Add spunvm.img in fastboot flash build_scriptTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: I8888889ca821be197f11eb58da9e5cd371908e0e			

#13 - 2023-04-28 18:44 - CD BSP-杜磊

- Status changed from New to 分析&分解中 In Analysis

#14 - 2023-05-08 14:13 - CD BSP-杜磊

- File logo_gen.py added

#15 - 2023-05-11 10:35 - CD BSP-杜磊

- Status changed from 分析&分解中 In Analysis to 完成 Closed

#16 - 2023-05-14 18:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199235	general/platform/vendor/qcom/kona	Pre_figure_turbox-c2130c-la1.1-vend o-r-dev	yepeng0322@thundersoft.com
BSP:OTA: Upgrade the partition used to save the user logoSelect the /bin/load_spunvm_img as the postinstall scriptTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Ic517630c9a27b72535a4d1ce259601aa8deab185			

#17 - 2023-05-14 18:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199237	general/device/qcom/vendor-commo n	Pre_figure_turbox-c2130c-la1.1-vend o-r-dev	yepeng0322@thundersoft.com
BSP:OTA: Upgrade the partition used to save the user logoAdd the postinstall action to the payload when it is generatedTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Ifce7bd48c7a91e51981d9871c858fac1bdebd963			

#18 - 2023-05-14 18:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199738	general/device/qcom/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vend o-r-dev	yepeng0322@thundersoft.com

		r-dev	
BSP:OTA: Allow postinstall to access block_deviceAllow postinstall to access block_deviceTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Iec725717892b77097a30ab88053c4c92fa287429			

#19 - 2023-05-14 18:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199937	general/platform/vendor/thundercom/spunvm_postinstall	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yepeng0322@thundersoft.com
BSP:OTA: Add postinstall trigger and load_spunvm_img scriptAdd postinstall trigger and load_spunvm_img scriptTC-RID: 1201-0100501IssueID: TS-R-DF-117668Change-Id: Iccf3c4deeece7e22cfc24f476419379f6ccac57e			

Files

logo_gen.py	4.04 KB	2023-05-08	CD BSP-杜磊
-------------	---------	------------	-----------