

Figure - Bug #117725

【BSP】 【DVT】 【OTA】 OTA升级后，APP 图标等没有更新成最新的图标设定

2023-04-28 15:26 - 移动测试一组_CDTs 刘强

Status:	CLOSED	Start date:	2023-04-28
Priority:	High	Due date:	
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0094-0095
Resolution:	FIXED	Degrated:	No
Severity:	Critical	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-05-04
Test Type:	ST	Root cause:	编码问题
Description			
前置条件			
None			
操作步骤：			
1.设备烧写0094版本			
2.通过中控升级到0095版本			
3.重启后查看设备显示			
预期结果：			
设备功能、界面均更新为最新版本集成功能			
实际结果：			
升级0095版本后，app图标等未更新为最新的图标			

History

#1 - 2023-04-28 15:28 - 移动测试一组_CDTs 刘强

- File 20230428-152806.jpg added

- File 20230428-152731.jpg added

#2 - 2023-04-28 15:50 - CD FW 曹覃刚

- Category changed from CD-FW to CD-APP

#3 - 2023-05-02 15:30 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
197152	general/platform/frameworks/libs/syste mui	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hong.wang_a@thundersoft.com
AF:Launcher:update icon db versionTC-RID: 1201-020530IssueID: TS-R-BUG-117725Change-Id: I135d5103e577660f065f749762c8e89c218ed21b			

#4 - 2023-05-04 09:43 - CD APP-王营

- Status changed from New to RESOLVED

- Assignee changed from CD APP-王营 to 移动测试一组_CDTs 刘强

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-04
- Root cause set to 编码问题

■ Current conclusion

问题已解决，待验证

■ My analysis

Launcher加载桌面icon使用了数据库缓存数据，需要清空缓存数据或者每次OTA升级时提高数据库版本号。

当前处理方案：升级数据库版本

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/libs/systemui/+197152>

#5 - 2023-05-04 18:46 - 移动测试一组_CDTS 刘强

- Status changed from RESOLVED to VERIFIED

0078-0097：不复现

0086-0097：不复现

0090-0097：不复现

验证通过

#6 - 2023-05-04 18:46 - 移动测试一组_CDTS 刘强

- Status changed from VERIFIED to CLOSED

#7 - 2023-05-05 21:20 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
197685	general/platform/frameworks/libs/syste mui	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_v8.5	wangxl0510@thundersoft.com
AF:Launcher:update icon db versionTC-RID: 1201-0205301IssueID: TS-R-BUG-117725Change-Id: I135d5103e577660f065f749762c8e89c218ed21b(cherry picked from commit 85a8dee304fda52d5960aae520a3535cc2f3e0c1)			

Files

20230428-152806.jpg	158 KB	2023-04-28	移动测试一组_CDTS 刘强
20230428-152731.jpg	84 KB	2023-04-28	移动测试一组_CDTS 刘强