

Figure - Bug #117733

测试 Test-ST # 113421 (New): V4.0功能与专项测试

测试 Test-ST # 113422 (New): V4.0专项--AF专项--monkey测试

【AF】 【EVT3】 【Monkey】 Monkey测试48小时， 出现CRASH: com.android.documentsui (1)

2023-05-04 10:20 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-05-04
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0095
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0098
Severity:	Critical	Fixed Version:	2023-05-05
Reproducibility:	Rarely	Root cause:	AOSP问题
Test Type:	Monkey Test		
Description			
【执行命令】 adb shell monkey --pkg-blacklist-file /sdcard/blacklist.txt --ignore-crashes --ignore-timeouts --ignore-security-exceptions --monitor-native-crashes --ignore-native-crashes -s 20 --throttle 500 --pct-touch 30 --pct-motion 15 --pct-nav 15 --pct-majornav 15 --pct-syskeys 5 --pct-appswitch 10 --pct-anyevent 10 --ignore-crashes -v -v 25000000 2>/sdcard/error.txt 1>/sdcard/info.txt CRASH: com.android.documentsui (pid 5105) // Short Msg: java.lang.NullPointerException // Long Msg: java.lang.NullPointerException: Attempt to invoke virtual method 'void android.view.View.setPressed(boolean)' on a null object reference // Build Label: HiPhi/PassengerDisplay_CN/PassengerDisplay:12/SKQ1.220201.001/3052:user/test-keys // Build Changelist: 3052 // Build Time: 1682619940000 // java.lang.NullPointerException: Attempt to invoke virtual method 'void android.view.View.setPressed(boolean)' on a null object reference // at com.android.internal.widget.DecorCaptionView.onTouchEvent(DecorCaptionView.java:231) // at android.view.View.dispatchTouchEvent(View.java:14541) // at android.view.ViewGroup.dispatchTransformedTouchEvent(ViewGroup.java:3114) // at android.view.ViewGroup.dispatchTouchEvent(ViewGroup.java:2787) // at android.view.ViewGroup.dispatchTransformedTouchEvent(ViewGroup.java:3120) // at android.view.ViewGroup.dispatchTouchEvent(ViewGroup.java:2801) // at com.android.internal.policy.DecorView.superDispatchTouchEvent(DecorView.java:516) // at com.android.internal.policy.PhoneWindow.superDispatchTouchEvent(PhoneWindow.java:1890) // at android.app.Dialog.dispatchTouchEvent(Dialog.java:864) // at androidx.appcompat.view.WindowCallbackWrapper.dispatchTouchEvent(WindowCallbackWrapper.java:69) // at com.android.internal.policy.DecorView.dispatchTouchEvent(DecorView.java:474) // at android.view.View.dispatchPointerEvent(View.java:14800) // at android.view.ViewRootImpl\$ViewPostImeInputStage.processPointerEvent(ViewRootImpl.java:6362) // at android.view.ViewRootImpl\$ViewPostImeInputStage.onProcess(ViewRootImpl.java:6163) // at android.view.ViewRootImpl\$InputStage.deliver(ViewRootImpl.java:5641) // at android.view.ViewRootImpl\$InputStage.onDeliverToNext(ViewRootImpl.java:5698) // at android.view.ViewRootImpl\$InputStage.forward(ViewRootImpl.java:5664) // at android.view.ViewRootImpl\$AsyncInputStage.forward(ViewRootImpl.java:5829) // at android.view.ViewRootImpl\$InputStage.apply(ViewRootImpl.java:5672) // at android.view.ViewRootImpl\$AsyncInputStage.apply(ViewRootImpl.java:5886) // at android.view.ViewRootImpl\$InputStage.deliver(ViewRootImpl.java:5645)			

```
// at android.view.ViewRootImpl$InputStage.onDeliverToNext(ViewRootImpl.java:5698)
// at android.view.ViewRootImpl$InputStage.forward(ViewRootImpl.java:5664)
// at android.view.ViewRootImpl$InputStage.apply(ViewRootImpl.java:5672)
// at android.view.ViewRootImpl$InputStage.deliver(ViewRootImpl.java:5645)
// at android.view.ViewRootImpl.deliverInputEvent(ViewRootImpl.java:8585)
// at android.view.ViewRootImpl.doProcessInputEvents(ViewRootImpl.java:8536)
// at android.view.ViewRootImpl.enqueueInputEvent(ViewRootImpl.java:8504)
// at android.view.ViewRootImpl$WindowInputEventReceiver.onInputEvent(ViewRootImpl.java:8708)
// at android.view.InputEventReceiver.dispatchInputEvent(InputEventReceiver.java:260)
// at android.os.MessageQueue.nativePollOnce(Native Method)
// at android.os.MessageQueue.next(MessageQueue.java:335)
// at android.os.Looper.loopOnce(Looper.java:161)
// at android.os.Looper.loop(Looper.java:288)
// at android.app.ActivityThread.main(ActivityThread.java:7880)
// at java.lang.reflect.Method.invoke(Native Method)
// at com.android.internal.os.RuntimeInit$MethodAndArgsCaller.run(RuntimeInit.java:548)
// at com.android.internal.os.ZygoteInit.main(ZygoteInit.java:1009)
//
```

History

#1 - 2023-05-04 10:24 - CD TEST-方永红

- File error.txt added

#2 - 2023-05-04 10:52 - CD APP-王营

- Status changed from New to ASSIGNED

- Assignee changed from CD APP-王营 to CD APP-王宏

#3 - 2023-05-04 17:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197395	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:DocumentsUI:Fixed monkey crashTC-RID: 1201-0300801IssueID: TS-R-BUG-117733Change-Id: Ifaf936b22e2beadbb31875becbcd7ea1cff2971d			

#4 - 2023-05-04 17:33 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD APP-王宏 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Fixed Version set to 2023-05-05

- Root cause set to AOSP问题

■ Current conclusion

已提交

■ My analysis

变成员变量为局部变量，不让成员变量的修改影响到方法内的调用

■Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+197395>

#5 - 2023-05-08 17:20 - CD TEST-方永红

5.8

0095（带开机动画版未复现）

#6 - 2023-05-09 09:58 - CD TEST-方永红

5.9

0507DB未复现

#7 - 2023-05-10 10:55 - CD TEST-方永红

- Status changed from *RESOLVED* to *VERIFIED*

- Verified Version set to *FlatBuild_HH_MCE_FSE.M.R.user.01.00.0098.C103(X103)*

5.10

0098未复现

先关闭

#8 - 2023-05-10 10:56 - CD TEST-方永红

- Status changed from *VERIFIED* to *CLOSED*

Files			
tlog_iov0201017500006162025411a2212290000002151_000039_0503182417.tar.gz	5.59 MB	2023-05-04	CD TEST-方永红
error.txt	382 KB	2023-05-04	CD TEST-方永红