

Status:	CLOSED	Start date:	2023-05-04
Priority:	Normal	Due date:	
Assignee:	物联网项目组-RD3_CDTS 周飞	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0094.c103
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
环境信息】EE环境 【问题出现时间】：20230428 15：34 【前提条件】：车机上电 【操作步骤】1.主界面点击相册 2.选择一张图片 3.点击左下角编辑按钮 4.点击右上角的三个点 5.点击导出按钮 6.长按修改尺寸大小输入框 【实际结果】1.1.进入相册 2.选中图片 3.进入图片编辑页面 4.弹出下拉框 5.进入平面导出图片页面 6.输入光标在输入法键盘显示 【期望结果】 1.进入相册 2.选中图片 3.进入图片编辑页面 4.弹出下拉框 5.进入导出平面图片页面 6.唤起输入法键盘 【备注】： 【影响版本】：01.00.0094.c103 【硬件版本号】：			

对比原生输入法和搜狗输入法

原生输入法软键盘高度较低，可以将整体dialog顶上去，不会出现遮挡。
搜狗输入法在dialog存在输入框的情况下采取全屏措施，不影响输入展示

■ Next action

转给百度输入法修改

#2 - 2023-05-05 17:41 - CD APP-王营
- File 原生输入法.jpg added
- File 搜狗输入法.jpg added

搜狗输入法和原生输入法对比截图已上传

#3 - 2023-08-22 09:54 - CDTS_TEST 王成
- Status changed from New to RESOLVED

- 1、系统粘贴气泡层级高于输入法，气泡部分不属于输入法范畴，需要系统适配
- 2、输入框遮挡问题，属于新需求

#4 - 2023-08-22 09:54 - CDTS_TEST 王成
- Status changed from RESOLVED to VERIFIED

#5 - 2023-08-22 09:54 - CDTS_TEST 王成
- Status changed from VERIFIED to CLOSED

Files			
d4c6c91d-5e67-469b-89c9-187eff4c2b7f.jpg	204 KB	2023-05-05	CDTS_Test 吴诗雨
原生输入法.jpg	162 KB	2023-05-05	CD APP-王营
搜狗输入法.jpg	144 KB	2023-05-05	CD APP-王营