

Status:	CLOSED	Start date:	2023-05-05
Priority:	Normal	Due date:	2023-05-15
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0095
Resolution:	FIXED	Degraded:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0101
Reproducibility:	Every time	Fixed Version:	2023-05-17
Test Type:	ST	Root cause:	功能实现
Description			
【前提条件】 None			
【测试步骤】 1. 烧写0095版本 2. 设备开机到工厂模式选择界面（汽车图片界面） 3. 同时按四个角进入工厂模式			
【预期结果】 3.1 进入工厂模式后，fan应该自动旋转，DTC上报正常 3.2 挡住风扇后，报异常code			
【实际结果】 3 进入工厂模式后，fan没有自动转起来			
kernel.txt Magnifier (346 KB) Delete 移动测			

History
#1 - 2023-05-06 18:50 - CD TPM-王祥林 - Assignee changed from CD TPM-王祥林 to CD BSP 叶鹏
叶鹏
处理一下这个节点的写权限。 java.io.FileNotFoundException: /sys/devices/platform/vendor/vendor:pwm-fan/hwmon/hwmon1/pwm1: open failed: EACCES (Permission denied)
#2 - 2023-05-15 19:33 - CDTs-TEST 周婷 - Due date set to 2023-05-15
#3 - 2023-05-16 19:21 - CD BSP 叶鹏 - Status changed from New to RESOLVED - % Done changed from 0 to 90
#4 - 2023-05-16 19:22 - CD BSP 叶鹏

- Assignee changed from CD BSP 叶鹏 to CD FW-廖涛

#5 - 2023-05-17 09:54 - CD FW-廖涛

- Status changed from RESOLVED to ASSIGNED

#6 - 2023-05-17 10:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
200515	general/platform/vendor/thundercom/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:FactoryMode: Add MCU info and modify fun get logical.TC-RID: 1201-0207601IssueID: TS-R-BUG-117769Change-Id: I69a376bc746eab2acce114e7fd04a66f250c9aed			

#7 - 2023-05-17 10:21 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to 移动测试一组\_CDTS 刘强
- % Done changed from 90 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-17
- Root cause set to 功能实现

Current conclusion  
已处理，代码已入库。

My analysis  
-

Next action  
测试验证。

#8 - 2023-05-18 14:14 - 物联网测试组\_TSCD 王维

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild\_HH\_MCE\_FSE.M.R.user.01.00.0101.C103(X103)

检测逻辑：  
进入工厂模式页面，会打开风扇，然后等待 5s，获取风扇转速，获取完成后关闭风扇；且只获取一次，如果一直停留在页面，风扇转速不会刷新

#9 - 2023-05-18 14:15 - 物联网测试组\_TSCD 王维

- Status changed from VERIFIED to CLOSED