

Status:	CLOSED	Start date:	2023-05-06
Priority:	Normal	Due date:	2023-06-16
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0094.c103
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【环境信息】EE环境 【问题出现时间】：20230505 10：56 【前提条件】：车机上电，副屏打开小窗应用 【操作步骤】 1. 中控播放冥想中的动画视频，查看副屏 【实际结果】 副屏同步播放中控所播放的动画视频，但上方显示状态栏 【期望结果】 沉浸情况下，副屏全屏播放中控的动画视频，不显示状态栏 【车架号】： 【备注】： 视频地址： 【影响版本】：01.00.0094.c103 【硬件版本号】：/ 【是否能恢复】：			

History
#1 - 2023-05-06 18:12 - CD TPM-王祥林
- Category set to CD-FW
- Assignee changed from CD TPM-王祥林 to CD FW-程天颖
#2 - 2023-05-08 11:42 - CD FW-程天颖
- Category changed from CD-FW to 依赖客户及其供应商解决
- Status changed from New to ASSIGNED
- Assignee changed from CD FW-程天颖 to CDTS_Test 吴诗雨
我们无该需求，初步分析可能是客户的三屏联动需求。请联系客户的副屏需求阮馨怡确认
#3 - 2023-05-09 16:00 - CDTS_Test 吴诗雨

- Status changed from ASSIGNED to RESOLVED

#4 - 2023-05-09 16:00 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#5 - 2023-05-09 16:01 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

#6 - 2023-05-18 21:52 - CDTS_TEST 王成

- Assignee changed from CDTS_Test 吴诗雨 to CD FW-程天颖

按照定义，状态栏和dock不应该显示，请看下是三屏联动的问题还是副屏的问题

#7 - 2023-05-19 11:33 - CDTS_TEST 王成

- Status changed from CLOSED to New

#8 - 2023-05-19 14:54 - CD FW-程天颖

- Assignee changed from CD FW-程天颖 to CDTS_TEST 王成

三屏联动的问题，需要app内处理，和系统无关

#9 - 2023-05-22 14:17 - CDTS_TEST 王成

- Category changed from 依赖客户及其供应商解决 to CD-FW

- Assignee changed from CDTS_TEST 王成 to CD FW 曹覃刚

确认需求：car show模式下，需要让副屏touch disable

#10 - 2023-05-24 20:27 - CDTS-TEST 周婷

- Due date set to 2023-06-16

#11 - 2023-05-24 20:31 - CD FW 曹覃刚

- Status changed from New to ASSIGNED

确认需求：car show模式下，需要让副屏touch disable

新的需求，0616

#12 - 2023-05-24 20:32 - CD FW 曹覃刚

- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#13 - 2023-06-19 15:25 - CD FW-鲁凯峰

HiPhiShow播放步骤

1. 先打开中控的工程模式
- adb root
- adb shell am start -n com.hryt.engineeringmode/com.hryt.engineeringmode.MainActivity
2. adb shell pkill brain
3. 打开HiPhiplay,点击右下角Local,设置成Local On

#14 - 2023-06-19 15:58 - CD FW-鲁凯峰

■ Current conclusion

新的需求已经完成,禁止所有的手势,通知显示

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+208370>

#15 - 2023-06-19 20:19 - CD FW-廖涛

- Category changed from CD-FW to 依赖客户及其供应商解决

- Status changed from ASSIGNED to NEED_INFO

- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨

■ Next action

测试确认并同步客户 , 或直接在 JIRA 上跟踪。

#16 - 2023-06-19 21:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208370	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:HiPhiShow: disable all notifications and gestureTC-RID: 1201-0204401IssueID: TS-R-BUG-117777Change-Id: If71b22eccfb18030ad707996170a74008078667d			

#17 - 2023-06-20 22:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208866	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxi0510@thundersoft.com
AF:HiPhiShow: disable all notifications and gestureTC-RID: 1201-0204401IssueID: TS-R-BUG-117777Change-Id: If71b22eccfb18030ad707996170a74008078667d(cherry picked from commit 410595eeb073fadd5b780cb8168afea18a4af68a)			

#18 - 2023-07-04 18:23 - CDTS_TEST 王成

- Status changed from NEED_INFO to RESOLVED

需求变更，客户验证通过

#19 - 2023-07-04 18:24 - CDTS_TEST 王成
- Status changed from RESOLVED to VERIFIED

#20 - 2023-07-04 18:24 - CDTS_TEST 王成
- Status changed from VERIFIED to CLOSED

Files			
副屏同步播放中控的视频时还显示状态栏.jpg	854 KB	2023-05-06	CDTS_Test 吴诗雨
10点56分副屏播放中控的动画视频时，还显示状态栏.7z	135 KB	2023-05-06	CDTS_Test 吴诗雨