

Status:	CLOSED	Start date:	2023-05-08
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	中控版本：03.02.0076.C101
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-05-08
Test Type:	ST	Root cause:	AOSP 原生没有多语言。
Description			
【问题描述】：副屏设置中搜索，有显示英文			
【前置条件】：车辆上电			
【软件/网络环境】：EE环境			
【软件版本】：IDCM 03.02.0076.C101			
【操作步骤】：1.副屏设置中搜索			
【预期结果/行为】：没有显示英文			
【实际结果/行为】：有显示英文			
【问题发生频率】：必现			
【实车VIN】：LJD8BC3F7P0000360			
【发生日期 & 时间】：2023/05/06 11:07			
【数采仪编号】：0300136			
【视频链接】：见附件			

History

#1 - 2023-05-08 18:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
198307	general/platform/packages/apps/SettinsIntelligence	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:SettingsIntelligence: Add Chinese strings.TC-RID: 1201-0201813IssueID: TS-R-BUG-117810Change-Id: I676acc6982d6c55c4ede880aa9aeba4d5d935fb9

- #2 - 2023-05-08 18:51 - CD FW-廖涛
- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CDTs_Test 吴诗雨

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-05-08

- Root cause set to AOSP 原生没有多语言。

■ Current conclusion

已处理，代码已入库。

■ My analysis

AOSP 原生没有多语言。已增加中文简体和繁体支持。

■ Next action

测试验证。

#3 - 2023-05-09 14:17 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to NEED_INFO

5/9版本验证通过，待客户验证后关闭

#4 - 2023-05-17 16:07 - CDTS_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

#5 - 2023-05-17 16:07 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#6 - 2023-05-17 16:07 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

无标题.png	562 KB	2023-05-08	CDTS_Test 吴诗雨
---------	--------	------------	---------------