

Status:	CLOSED	Start date:	2023-05-11
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	副屏版本：01.00.0095.c103
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-05-17
Reproducibility:	Rarely	Root cause:	编码问题
Test Type:	ST		
Description			
【环境信息】 EE环境 【问题出现时间】：20230511 8:35 【前提条件】：车机上电，5月10日晚8点半运行monkey 1. 5月11日8点30分左右停止monkey进程运行 2. 检查副屏状态 【实际结果】 副屏中的应用图标变小，dock栏的四个应用图标不是平均分布，居于偏上位置 【期望结果】 副屏中的应用图标变小，dock栏的四个应用图标不是平均分布 【车架号】： 【备注】： monkey运行，偶发问题。没有确切的手顺进行复现。但副屏设置中没有关于设置图标大小的入口，所以不应该出现图标变小的现象。 log地址：https://ofs.human-horizons.com/#/download/index/YGavaLRm0dc%3D 视频地址：https://ofs.human-horizons.com/#/download/index/ZMAI0LsuvpY%3D 【影响版本】：副屏：01.00.0095.c103 【硬件版本号】：/ 【是否能恢复】：			
Related issues:			
Related to Figure - Bug # 117847: 【IOV-27171】 【AF】 【EVT3】 【桌...			CLOSED 2023-05-09

History

#1 - 2023-05-11 18:33 - CDTs_Test 吴诗雨

log：ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_117888

#2 - 2023-05-15 19:28 - CD APP-王营

- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王莹 to CD APP-王宏

#3 - 2023-05-16 11:21 - CD APP-王宏

此问题跟随以下一起解决
<https://share.thundersoft.com/redmine/issues/117847>

#4 - 2023-05-16 16:28 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CDTS_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-05-17
- Root cause set to 编码问题

#5 - 2023-05-19 09:44 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to NEED_INFO

#6 - 2023-05-23 18:10 - CDTS_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

#7 - 2023-05-23 18:11 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#8 - 2023-05-23 18:11 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

停止monkey后，副屏应用图标变小.mp4	16.2 MB	2023-05-11	CDTS_Test 吴诗雨
------------------------	---------	------------	---------------