

Figure - Bug #117954

【BSP】 【EVT1】 【ST】 【Display】 0515 db版本, VX1 执行adb reboot 重启到开机操作界面后会自动黑屏一次, 然后恢复

2023-05-16 14:34 - 移动测试一组_CDTS 刘强

Status:	CLOSED	Start date:	2023-05-16
Priority:	High	Due date:	
Assignee:	移动测试一组_CDTS 刘强	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103.202305150054
Need_Info:	--	Degraded:	--
Resolution:	--	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	EVT1硬件版本不稳定
Test Type:	ST		
Description			
【前提条件】 None			
【测试步骤】 1. 烧写FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103.202305150054版本 2. 设备开机后执行adb reboot 3. 重启后查看设备现象			
【预期结果】 3. 显示正常			
【实际结果】 3, VX1板子设备重启进入操作系统界面后, 会再次自动黑屏一次			

History

#1 - 2023-05-18 10:17 - CD BSP-杜磊

- Status changed from New to NEED_INFO
- Assignee changed from CD BSP-杜磊 to 移动测试一组_CDTS 刘强
- % Done changed from 0 to 80

请使用最新的DB版本进行验证, 不要使用EVT1的硬件版本, 建议使用完整的较新的硬件版本进行测试。

#2 - 2023-05-19 14:57 - 移动测试一组_CDTS 刘强

- Assignee changed from 移动测试一组_CDTS 刘强 to CD BSP-杜磊

验证版本: 0100

验证结果: 使用新硬件DVT 测试20次未复现

#3 - 2023-05-19 15:17 - CD BSP-杜磊

- Status changed from NEED_INFO to RESOLVED
- Assignee changed from CD BSP-杜磊 to 移动测试一组_CDTS 刘强

- % Done changed from 80 to 100
- Root cause set to EVT1硬件版本不稳定

#4 - 2023-05-19 19:40 - 移动测试一组_CDTS 刘强

- Status changed from RESOLVED to VERIFIED

EVT1问题，新硬件不复现关闭

#5 - 2023-05-19 19:40 - 移动测试一组_CDTS 刘强

- Status changed from VERIFIED to CLOSED

Files			
kernal1.txt	324 KB	2023-05-16	移动测试一组_CDTS 刘强
display1.txt	1.77 MB	2023-05-16	移动测试一组_CDTS 刘强