

Figure - Bug #117963

【IOV-27900】【VC1】【0095】【台架】【EE环境】【副屏】副屏在打开设置界面搜索框输入时，屏幕右边会自动来回弹出音乐音量设置条

2023-05-16 17:00 - CDTs\_TEST 王成

|                         |               |                   |                 |
|-------------------------|---------------|-------------------|-----------------|
| Status:                 | CLOSED        | Start date:       | 2023-05-16      |
| Priority:               | Normal        | Due date:         |                 |
| Assignee:               | CDTS_Test 吴诗雨 | % Done:           | 0%              |
| Category:               | AUDIO-FW      | Estimated time:   | 0.00 hour       |
| Target version:         |               | Found Version:    | 01.00.0095.c103 |
| Need_Info:              | --            | Degrated:         | --              |
| Resolution:             | --            | Verified Version: |                 |
| Severity:               | Normal        | Fixed Version:    |                 |
| Reproducibility:        | Every time    | Root cause:       |                 |
| Test Type:              | ST            |                   |                 |
| Description             |               |                   |                 |
| 环境信息】EE环境               |               |                   |                 |
| 【问题出现时间】：20230513 13：55 |               |                   |                 |
| 【前提条件】：副屏上电，网络正常        |               |                   |                 |
| 【操作步骤】                  |               |                   |                 |
| 1.点击副屏设置                |               |                   |                 |
| 2.点击上方搜索框               |               |                   |                 |
| 【实际结果】                  |               |                   |                 |
| 1.屏幕右边会来回自动弹出音乐音量设置条    |               |                   |                 |
| 【期望结果】                  |               |                   |                 |
| 1.搜索框正常进行输入             |               |                   |                 |
| 【备注】：                   |               |                   |                 |
| 副屏第103次开机               |               |                   |                 |
| 【应用版本】：                 |               |                   |                 |
| 【硬件版本号】：                |               |                   |                 |
| 【中控版本号】：03.02.0076.x101 |               |                   |                 |
| 【副屏版本号】：01.00.0095.c103 |               |                   |                 |

History

---

#1 - 2023-05-16 17:46 - CD FW 曹覃刚

- Category changed from CD-FW to 依赖客户及其供应商解决

- Status changed from New to NEED\_INFO

- Assignee changed from CD FW 曹覃刚 to CDTs\_TEST 王成

Hi 王成

在问题发生时, 收到了中控设置音量的消息

所以显示音量设置条, 是由于中控在调整音量, 请确认

-----

05-12 13:55:31.478 2029 17741 I MicroService: Receive message: SocketMessageBean{businessData='21930', srcService='IDCM\_CarAudioService', destService='FSEM\_AudioService', messageType='0', uuid='56498310681050',

```
payloadData={"srcService":"IDCM_CarAudioService","dstService":"FSEM_AudioService","methodName":"setVolume","messageType":0,"uuid":"56498310681050","parameters":{"functionInfo":{"IDCM_VolumeValue_Media":"25"}}}}
05-12 13:55:35.688 2029 17751 I MicroService: Receive message: SocketMessageBean{businessData='21930', srcService='IDCM_CarAudioService',
destService='FSEM_AudioService', messageType='0', uuid='56502513765892',
payloadData={"srcService":"IDCM_CarAudioService","dstService":"FSEM_AudioService","methodName":"setVolume","messageType":0,"uuid":"56502513765892","parameters":{"functionInfo":{"IDCM_VolumeValue_Media":"26"}}}}
05-12 13:55:54.163 2029 17795 I MicroService: Receive message: SocketMessageBean{businessData='21930', srcService='IDCM_CarAudioService',
destService='FSEM_AudioService', messageType='0', uuid='56520994461563',
payloadData={"srcService":"IDCM_CarAudioService","dstService":"FSEM_AudioService","methodName":"setVolume","messageType":0,"uuid":"56520994461563","parameters":{"functionInfo":{"IDCM_VolumeValue_Media":"25"}}}}
-----
```

#2 - 2023-05-17 16:10 - CDTS\_TEST 王成  
- Status changed from NEED\_INFO to RESOLVED

BUG已流转给中控处理

#3 - 2023-05-17 16:10 - CDTS\_TEST 王成  
- Status changed from RESOLVED to VERIFIED

#4 - 2023-05-17 16:10 - CDTS\_TEST 王成  
- Status changed from VERIFIED to CLOSED

#5 - 2023-05-18 21:14 - CDTS\_TEST 王成  
- Status changed from CLOSED to New  
- Assignee changed from CDTS\_TEST 王成 to CD FW 曹覃刚

今天最新出现这个问题抓取的日志地址：<https://ofs.human-horizons.com/#/download/index/OCwMIgFLP%2Fs%3D>

在连接蓝牙耳机时，断开连接会弹出音量设置条

#6 - 2023-05-18 21:15 - CDTS\_TEST 王成

```
TaoZhanTao ZHAN 占涛 添加了评论 - 2023/05/18 10:37
128539 05-17 14:20:18.105 1578 1763 I CAR.AUDIO.FSE: onReceiveData receiveData =
{"srcService":"FSEM_AudioService","dstService":"IDCM_CarAudioService","messageType":0,"uuid":"1684304417449945538","methodName":"getVolume","parameters":{"functionInfo":
{"IDCM_VolumeValue_Media":"MEDIA"}
}}
128540 05-17 14:20:18.105 1578 1763 I CAR.AUDIO.FSE: receiveDataFromFse methodName = getVolume
128541 05-17 14:20:18.105 1578 1763 I CAR.AUDIO.FSE: receiveDataFromFse volumeType = MEDIA
128544 05-17 14:20:18.105 1578 1763 I CAR.AUDIO.FSE: notifyVolumeValueToFse volume = 39
128545 05-17 14:20:18.105 1578 1763 I CAR.AUDIO.FSE: setDataToFse functionType = 8, parameter = 39
128546 05-17 14:20:18.105 1578 1763 I CAR.AUDIO.FSE: convertToJsonFormat =
{"srcService":"IDCM_CarAudioService","dstService":"FSEM_AudioService","methodName":"getVolume","messageType":1,"uuid":"1684304417449945538","parameters":{"functionInfo":
```

\*

{ "IDCM\_VolumeValue\_Media": "39" }

}}

128770 05-17 14:20:18.707 1578 1763 | CAR.AUDIO.FSE: onReceiveData receiveData =

{ "srcService": "FSEM\_AudioService", "dstService": "IDCM\_CarAudioService", "messageType": 0, "uuid": "1684304418050689652", "methodName": "isMute", "parameters": { "functionInfo":

{ "IDCM\_VolumeMute\_Media": "WHOLE\_VEHICLE" }

}}

128772 05-17 14:20:18.707 1578 1763 | CAR.AUDIO.FSE: receiveDataFromFse methodName = isMute

128773 05-17 14:20:18.707 1578 1763 | CAR.AUDIO.FSE: receiveDataFromFse muteType = WHOLE\_VEHICLE

128774 05-17 14:20:18.707 1578 1763 | CAR.AUDIO.FSE: notifyMuteStatusToFse muteStatus = false

128775 05-17 14:20:18.707 1578 1763 | CAR.AUDIO.FSE: setDataToFse functionType = 9, parameter = false

128776 05-17 14:20:18.707 1578 1763 | CAR.AUDIO.FSE: convertToJsonFormat =

{ "srcService": "IDCM\_CarAudioService", "dstService": "FSEM\_AudioService", "methodName": "isMute", "messageType": 1, "uuid": "1684304418050689652", "parameters": { "functionInfo":

\*

{ "IDCM\_VolumeMute\_Media": "false" }

}}

根据最新复现的log，主屏没有设置音量给副屏，请副屏调查一下音量条显示的原因

#7 - 2023-05-19 09:34 - CD FW 曹覃刚

- Category changed from 依赖客户及其供应商解决 to CD-FW

- Status changed from New to ASSIGNED

- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖

#8 - 2023-05-19 14:50 - CD FW-程天颖

- Assignee changed from CD FW-程天颖 to CD FW-廖涛

#9 - 2023-05-22 10:32 - CD FW-廖涛

- Assignee changed from CD FW-廖涛 to CDTS\_TEST 王成

■ Current conclusion

问题变更，且没有对应日志。

■ Next action

麻烦测试提供下对应的日志。

#10 - 2023-05-22 14:29 - CD FW-廖涛

- Assignee changed from CDTS\_TEST 王成 to CD FW-廖涛

#11 - 2023-05-22 14:41 - CD FW-廖涛

- Category changed from CD-FW to AUDIO-FW

- Assignee changed from CD FW-廖涛 to Multimedia组-RD3\_TSCD 梁卿山

■ Current conclusion

根据日志和现象看，在蓝牙耳机断开的时候，AudioService 会同步中控的音量及状态，然后显示了音量调节 UI。

日志如下：

```
11-11 00:02:33.139 1895 2056 I Avrcp_ext: storeVolume: Storing stream volume level for device 28:A5:3F:23:F4:A0 : 19
11-11 00:02:33.151 1076 1856 I AS.AudioDeviceBroker: handleBluetoothA2dpActiveDeviceChangeExt state=0 addr=28:A5:3F:23:F4:A0 prof=2 supprNoisy=false vol=-1
11-11 00:02:33.162 1076 1856 I AS.AudioDeviceBroker: msg: setBluetoothA2dpDeviceConnectionStateSuppressNoisyIntent state=0 addr=28:A5:3F:23:F4:A0 prof=2
supprNoisy=false vol=-1
11-11 00:02:33.181 1076 1853 D AS.AudioService: idcm_volume:syncIDCMicroAudioVolume bluetooth disconnected
11-11 00:02:33.181 1076 1853 D AudioIDCMicroNegotiator: idcm_volume:getIDCMicroVolume
11-11 00:02:33.206 1076 2677 D AudioIDCMicroNegotiator: idcm_volume:getIDCMicroVolume volume 10
11-11 00:02:33.207 1076 2677 D AudioIDCMicroNegotiator: idcm_volume:onSetIDCMicroVolume mIsTimeout= false value = 10 isRequested=false
11-11 00:02:33.207 1076 2677 D AS.AudioService: idcm_volume:onSetIDCMicroVolume: 10
11-11 00:02:33.782 1076 1853 D AudioIDCMicroNegotiator: idcm_volume:getIDCMicroAudioMute
11-11 00:02:33.919 1915 2326 I vol.Events: writeEvent active_stream_changed STREAM_MUSIC
11-11 00:02:33.920 1076 2646 D AudioIDCMicroNegotiator: idcm_volume:getIDCMicroAudioMute mute false
11-11 00:02:33.920 1076 2646 D AudioIDCMicroNegotiator: idcm_volume:onSetIDCMicroAudioMute mIsTimeout= false value = mute_off isRequested=false
11-11 00:02:33.920 1076 2646 D AS.AudioService: idcm_volume:onSetIDCMicroAudioMute: mute_off
11-11 00:02:33.982 1915 2326 I vol.Events: writeEvent level_changed STREAM_MUSIC 10
11-11 00:02:34.124 1915 1915 I vol.Events: writeEvent show_dialog volume_changed keyguard=false
11-11 00:02:34.388 1915 2326 I vol.Events: writeEvent level_changed STREAM_SYSTEM 2
11-11 00:02:34.389 1915 2326 I vol.Events: writeEvent level_changed STREAM_VOICE_CALL 2
11-11 00:02:34.393 1915 1915 I vol.Events: writeEvent show_dialog volume_changed keyguard=false
11-11 00:02:37.393 1915 1915 I vol.Events: writeEvent dismiss_dialog timeout
11-11 00:02:37.396 1915 2326 I vol.Events: writeEvent active_stream_changed UNKNOWN_STREAM_-1
```

■ Next action

麻烦卿山看下怎么处理。

#12 - 2023-05-22 18:54 - Multimedia组-RD3\_TSCD 梁卿山

HI ALL

当前分析：

副屏在蓝牙断开后，会主动获取当前中控的音量，  
然后设置到副屏，这时会弹出UI变化，该部分还在咨询客户，是否需要修改。

#13 - 2023-05-24 14:45 - Multimedia组-RD3\_TSCD 梁卿山

- File 音量UI.png added

- Assignee changed from Multimedia组-RD3\_TSCD 梁卿山 to CDTS\_Test 吴诗雨

HI 诗雨

该问题和客户确认，音量调节的提示暂时保留。

#14 - 2023-05-24 15:39 - CDTS\_Test 吴诗雨

- Status changed from ASSIGNED to RESOLVED

#15 - 2023-05-24 15:40 - CDTS\_Test 吴诗雨  
- Status changed from RESOLVED to VERIFIED

#16 - 2023-05-24 15:40 - CDTS\_Test 吴诗雨  
- Status changed from VERIFIED to CLOSED

| Files                                                                    |         |            |                          |
|--------------------------------------------------------------------------|---------|------------|--------------------------|
| 飞书20230513-100207.mp4                                                    | 1.87 MB | 2023-05-16 | CDTS_TEST 王成             |
| tlog_iov0201017500006162025411a2212290000000601_000103_0512135615.tar.gz | 10.7 MB | 2023-05-16 | CDTS_TEST 王成             |
| 音量UI.png                                                                 | 88.8 KB | 2023-05-24 | Multimedia组-RD3_TSCD 梁卿山 |