

Status:	CLOSED	Start date:	2023-05-18
Priority:	High	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	副屏版本：95 usedebug版本
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Occasionally	Root cause:	
Test Type:	ST		
Description			
【前提条件】 1、车机已上电，网络正常 2、车辆处于测试环境 【操作手順】 1、进入副屏遥控器应用，音量条处于非静音状态 2、滑动音量条按钮 【实际结果】 2、等待几秒中，音量条会回弹到之前的参数 【期望结果】 2、不会回弹 【复归方法】无 【复现率】5/5 测试时间：20230517 17：06 副屏版本：95 usedebug版本 副屏和主屏的日志请见附件，测试视频请见附件			

History
#1 - 2023-05-18 18:49 - CDTs_Test 吴诗雨
17：06~17：07时间点只发送了一次音量调节
Line 457971: 05-17 17:07:06.842 D/RemoteControlClient_SocketMessageUtil(28170): Send message to service finished. direction: 1, messageType: 19, json: {"type":"music","source":0,"token":"ki0sCMqFgE3bJZf","value":7}
麻烦协调遥控器SDK同事帮忙分析一下回弹问题
#2 - 2023-05-18 21:00 - CDTs-TEST 周婷
- Priority changed from Normal to High
- Severity changed from Normal to Major
#3 - 2023-05-19 14:49 - CD FW-程天颖

- Assignee changed from CD FW-程天颖 to CD FW-廖涛

#4 - 2023-05-19 15:39 - CD FW-廖涛

- Status changed from New to NEED_INFO

- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨

■ Current conclusion

从副屏的日志看，在 17:06 - 17:07 之间，接收到 10 次设置音量的请求。

从中控的日志看，日志出现的断层，如下：

05-17 17:06:27.878 D/CompatibilityChangeReporter(1280): Compat change id reported: 143937733; UID 10043; state: ENABLED
05-17 17:06:27.879 D/JobScheduler(1280): pending queue: 0 jobs.
05-17 17:06:27.879 D/JobScheduler(1280): Pending queue:
05-17 17:06:56.149 I/ActivityManager(1280): Process com.hryt.whud (pid 27799) has died: cch+5 CEM
05-17 17:06:56.149 I/Zygote (443): Process 27799 exited due to signal 9 (Killed)
05-17 17:06:56.149 I/ActivityManager(1280): App has been killed ProcessRecord{dee15c1 27799:com.hryt.whud/u0a43}
05-17 17:06:56.149 I/ActivityManager(1280): Process: com.hryt.whud is in restart white list, should restart it.
05-17 17:06:56.149 I/libprocessgroup(1280): Successfully killed process cgroup uid 10043 pid 27799 in 0ms

从问题视频看，因为仅仅是遥控器底部的音量条变化，应该和副屏没有关系，副屏同步音量给中控，中控应该会展示左侧的音量条。

■ Next action

测试确认并同步客户。

#5 - 2023-05-23 19:37 - CDTS_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

#6 - 2023-05-23 19:37 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#7 - 2023-05-23 19:37 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
飞书20230517-171049.mp4	9.59 MB	2023-05-18	CDTS_Test 吴诗雨
副屏-17-06.log	2.52 MB	2023-05-18	CDTS_Test 吴诗雨
主屏-17-06.7z	2.4 MB	2023-05-18	CDTS_Test 吴诗雨