

Figure - Bug #118178

【IOVDEV-29914】 【内部】 【VC1】 【0095】 【台架】 【EE环境】 【副屏】 设置中调节字体大小后，音乐界面字体大小显示不一

2023-05-23 14:02 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-05-23
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	副屏：01.00.0095.c103 中控：03.02.0080.C101
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【环境信息】 EE环境 【问题出现时间】：20230523 10点22分（第159次开机） 【前提条件】：车机上电（KL30ON，KL15 ON，已连接中控和功放，可正常输出声音） 1.中控设置-显示中，字体大小调节到最大 2.进入本地音乐播放器界面，点击左上角列表按钮，显示“音乐人”、“专辑”、“歌曲”、“播放列表”、“音效”等 【实际结果】 其中的“音效”字体与其它字体不一致 【期望结果】 “音效”字体与其它字体显示一致，符合设置字体大小要求。 【备注】： 设置-显示中调节字体至最小，“音效”显示也与其它字体不一致。 车架号VIN：HRYTTTESTVINMGM400 中控端log可从云端获取 副屏log地址：https://ofs.human-horizons.com/#/download/index/Dzlpkn8EnjY%3D 【影响版本】：副屏：01.00.0095.c103 中控：03.02.0080.C101 【硬件版本号】：/ 【是否能恢复】：			

History

#1 - 2023-05-23 14:10 - CDTS_Test 吴诗雨

ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_118178

#2 - 2023-05-23 16:09 - CD APP-王营

- Status changed from New to NEED_INFO

- Assignee changed from CD APP-王莹 to CDTS_Test 吴诗雨

音乐，相册，文件管理器原生应用不做定制，follow AOSP效果

#3 - 2023-05-23 16:46 - CDTS_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

#4 - 2023-05-23 16:46 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#5 - 2023-05-23 16:46 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

字体最大时显示不一致1.jpg	831 KB	2023-05-23	CDTS_Test 吴诗雨
字体最小时显示不一致2.jpg	915 KB	2023-05-23	CDTS_Test 吴诗雨