

Figure - Bug #118298
IOVDEV-30676 【内部】【VC1】【0100】【台架】【EE环境】【副屏】【蓝牙】副屏在于设备连接成功后，
可以修改设备名称超过20个字符，超过长度限制，与需求不符
2023-05-27 12:19 - CDTs-TEST 周婷

Status:	CLOSED	Start date:	2023-05-27
Priority:	Normal	Due date:	
Assignee:	CDTS-TEST 周婷	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.100.
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	2023-05-27
Test Type:	User Experience	Root cause:	需求理解有误。
Description			
【环境信息】EE环境 【问题出现时间】：20230526 09：39 【前提条件】：副屏上电；中控、功放已连接；副屏、中控时间一致 【操作步骤】 1.激活蓝牙耳机设备 2.打开副屏蓝牙 3.点击修改连接成功后的蓝牙设备名称 【实际结果】 1.修改设备名称长度超过20个字符的限制 【期望结果】 1.设备名称不超过20个字符的限制 【备注】： 第158次开机 蓝牙设备型号“ 安卓蓝牙耳机 日志、视频地址：https://ofs.human-horizons.com/#/download/index/%2FjdUIWLfnVo%3D 中控VIN号：HRYTTESTVINMGM817 【中控版本号】：03.02.0082.c101 【副屏版本号】：01.00.0100.c103			

History

#1 - 2023-05-27 12:20 - CDTs-TEST 周婷

log 飞书提供给廖涛

#2 - 2023-05-27 15:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203052	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Set remote bluetooth device name max length to 20.TC-RID: 1201-0201801IssueID: TS-R-BUG-118298Change-Id: Icbbe1f06c9cd27ab79bcd780bf897145643bfb5e			

- #3 - 2023-05-27 15:43 - CD FW-廖涛
- Status changed from New to RESOLVED
 - Assignee changed from CD FW-廖涛 to CDTS-TEST 周婷
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Fixed Version set to 2023-05-27
 - Root cause set to 需求理解有误。

■ Current conclusion

已处理，代码已入库。

■ My analysis

需求对齐。

■ Next action

测试验证。

- #4 - 2023-06-02 13:47 - SZTS_TEST 邹涛
- Status changed from RESOLVED to VERIFIED

在106版本验证通过

- #5 - 2023-06-02 13:48 - SZTS_TEST 邹涛
- Status changed from VERIFIED to CLOSED