

Figure - Bug #118433
IOVDEV-31808【内部】【VC1】【0100】【台架】【EE环境】【副屏】【第三方应用】taptap进入有效，使用小窗模式，再使用全屏模式，状态栏显示错误
2023-06-01 19:00 - 物联网测试组_CDTS 唐霞

Status:	CLOSED	Start date:	2023-06-01
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0100.C103
Resolution:	FIXED	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Occasionally	Fixed Version:	2023-06-07
Test Type:	User Experience	Root cause:	编码问题
Description			
【环境信息】：EE环境			
【问题出现时间】：2023/05/31 09:47 第176次开机			
【前提条件】：电源ON			
【操作步骤】：			
1、打开taptap			
2、进入游戏			
3、使用小窗模式			
4、再使用全屏模式			
【实际结果】			
状态栏显示错误			
【期望结果】			
状态栏显示正常			
【备注】：			
【应用版本】：			
【硬件版本号】：不涉及			
【副屏版本号】：01.00.0100.C103			
【中控版本号】：03.02.0086.C102.03_userdebug_2305271506			
【中控VIN】HRYTTESTVINMGM403			
【第三方应用版本号】taptap 2.56.0-rel100000			
录屏&log: https://ofs.human-horizons.com/#!/download/index/6yQ6zUcPi0U%3D			

History

- #1 - 2023-06-01 19:45 - CD APP-王营
- File screen-20230531-152724.mp4 added
- Category changed from CD-APP to CD-FW
- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营 to CD FW-廖涛

Hi 廖涛

请更新一下游戏列表，游戏不应该支持小窗模式

#2 - 2023-06-02 13:47 - CD FW-廖涛
- Category changed from CD-FW to CD-APP
- Assignee changed from CD FW-廖涛 to CD APP-王营

Hi, 王营：
从 TapTap 中打开的游戏，顶层 Activity 的包还是 TapTap，不能直接将 TapTap 当做游戏，需要在 Launcher 中单独处理下。

TapTap 游戏【无尽回廊】打开后的 RootTask 信息如下：

RootTask id=179 bounds=[0,0][2380,1020] displayId=0 userId=0
configuration={1.0 ?mcc?mnc [zh_CN] ldtr sw680dp w1586dp h625dp 240dpi lrg long hdr land finger -keyb/v/h -nav/h winConfig={ mBounds=Rect(0,0 - 2380, 1020)
mAppBounds=Rect(0,0 - 2380, 974) mMaxBounds=Rect(0,0 - 2380, 1020) mWindowingMode=fullscreen mDisplayWindowingMode=fullscreen
mActivityType=standard mAlwaysOnTop=undefined mRotation=ROTATION_0} s.10 fontWeightAdjustment=0}
taskId=179: com.taptap/com.taptap.sandbox.client.stub.ShadowActivity\$P0 bounds=[0,0][2380,1020] userId=0 visible=true
topActivity=ComponentInfo{com.taptap/com.taptap.sandbox.client.stub.ShadowActivity\$P0}

#3 - 2023-06-06 10:12 - CD APP-王营
- Assignee changed from CD APP-王营 to CD APP-王宏

to 王宏

请将taptap启动的内部有些task在Recent任务列表中进行过滤，如果是taptap打开的快速游戏，不在task右上角显示以小窗启动按钮。

#4 - 2023-06-06 15:30 - CD APP-王宏
- % Done changed from 0 to 50
- Root cause set to 编码问题

■ Current conclusion
已提交
■ My analysis
在taptap启动的游戏进程卡片中隐藏小窗button。
■ Submit URL
<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/205101>

#5 - 2023-06-06 16:36 - IoT scm
Gerrit Merge Information：

ID	Project	Branch	Uploader
205101	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com

#6 - 2023-06-06 16:38 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to 物联网测试组_CDTS 唐霞
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-06-07

#7 - 2023-06-14 16:52 - 物联网测试组_CDTS 唐霞

- Status changed from RESOLVED to VERIFIED

验证通过，关闭问题单

验证版本：user.01.00.0110.C104（6/13）

#8 - 2023-06-14 16:52 - 物联网测试组_CDTS 唐霞

- Status changed from VERIFIED to CLOSED

Files

screen-20230531-152724.mp4	15.8 MB	2023-06-01	CD APP-王营
----------------------------	---------	------------	-----------