

Figure - Bug #118563

Bug # 118503 (CLOSED): 【IOVDEV-32511】 【内部】 【VC1】 【0072】 【台架】 【EE环境】 【副屏】 副屏严重卡顿王者荣耀白屏，打开应用响应延迟太高，打开设置-黑屏-除下拉通知手势外其余手势无响应

解决王者荣耀和OTA进程的Selinux问题

2023-06-05 22:10 - CD TPM-王祥林

Status:	New	Start date:	2023-06-05
Priority:	Normal	Due date:	
Assignee:	CD BSP赖永惺	% Done:	20%
Category:	冻屏	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0106.C104
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Occasionally	Fixed Version:	
Test Type:	Free Test	Root cause:	
Description			
这个bug票里发现有很多王者荣耀和ota进程的Selinux错误，请处理一下。 https://share.thundersoft.com/redmine/issues/118503 log地址： ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_118503 ota进程：hht_ota_mgr			

History

#1 - 2023-06-06 22:54 - CD BSP赖永惺

- % Done changed from 0 to 20

Hi ALL

已提交代码，

<https://dev.thundercomm.com/gerrit/c/general/device/thundercomm/TCDEV/+205317>

本地正在编译验证中，没有问题话，准备Jenkins验证.

Thanks

Yongxing

#2 - 2023-06-08 17:12 - CDTs-TEST 周婷

- Category changed from BSP to 冻屏

#3 - 2023-06-09 18:48 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
205317	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	laiyx0702@thundersoft.com

