

Figure - Bug #118577
IOVDEV-32770【内部】【VC1】【106】【台架】【EE环境】【副屏】【遥控器】不同网络下，进入遥控器页弹出连接失败弹窗，点击连接失败弹窗，重新连接按钮，弹窗闪现
2023-06-06 16:27 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-06-06
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
环境信息】EE环境			
【问题出现时间】：20230605 19:32			
【前提条件】：副屏上电			
连接中控时间与副屏同步			
手机型号：iphone13promax			
IOS版本：15.6			
手机号：18629666668			
连接不同网络下			
副屏正常连接功放			
【操作步骤】			
1.移动设备和副屏连接不同网络，移动设备进入高合EEapp，			
2.点击高合ee状态栏hiphi模块，进入遥控器模块			
3.遥控器模块弹出连接失败弹窗，点击弹窗重新连接按钮			
【实际结果】			
1.移动设备和副屏连接不同网络，触发遥控器模块弹出连接失败弹窗，点击弹窗重新连接按钮，仍显示遥控器方向控制页面			
【期望结果】			
1.移动设备和副屏连接不同网络，触发遥控器模块，无法进入方向控制页			
【备注】：			
硬件版本号】：			
【高合ee版本】5.24.0（7）			

手机型号：iphone13promax

IOS版本：15.6

【当前开机次数】：副屏当前开机第232次

【中控版本号】：03.02.0088.C103

【副屏版本号】：01.00.0106.c104

IDCM VIN：HRYTTESTVINMGM402

SN：HRYTTESTVINID0402

建议性问题，建议修改

概率：次问题出现一次

History

- #1 - 2023-06-06 18:08 - CD FW-廖涛
- Category changed from CD-FW to 依赖客户及其供应商解决
- Status changed from New to NEED_INFO
- Assignee changed from CD FW-程天颖 to CD TEST-方永红
- Current conclusion
- 遥控器连接断开的弹窗以及是否显示方向控制界面都是有 高合EEapp 实现的，需要 高合EEapp 来处理。
- Next action
- 测试确认并同步客户。
- #2 - 2023-06-07 10:30 - CDTS_Test 吴诗雨
- Status changed from NEED_INFO to RESOLVED
- #3 - 2023-06-07 10:31 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED
- #4 - 2023-06-07 10:31 - CDTS_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

Files

_thumb_338647.png	20.8 KB	2023-06-06	CD TEST-方永红
20230605-19.32.32.txt	608 KB	2023-06-06	CD TEST-方永红
video(42).mp4	2.43 MB	2023-06-06	CD TEST-方永红