

Status:	CLOSED	Start date:	2023-06-07
Priority:	Urgent	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	卡顿	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	DUPLICATE	Degrated:	--
Severity:	Critical	Verified Version:	
Reproducibility:	Rarely	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
环境信息】EE环境 【问题出现时间】：20230607 13：21 【前提条件】：副屏上电，中控已连接 【操作步骤】 1. 【实际结果】 1.副屏又出现严重卡顿，三个多小时出现两次了 【期望结果】 1.副屏各功能正常，不会出现卡顿、冻屏、黑屏、花屏 【备注】： 【当前开机次数】：161 【应用版本】： 【硬件版本号】： 【VIN】HRYTTESTVINMGM401 【中控版本号】：03.02.0088.C103 【副屏版本号】：01.00.0106（01.00.0104）			
Related issues:			
Duplicates Figure - Bug # 118622: 【AF】【EVT3】【实车】系统卡顿		CLOSED	2023-06-07

History
#1 - 2023-06-07 22:16 - CD FW 曹覃刚
- Status changed from New to ASSIGNED

■ 我的分析

与 #118622 有相同的错误信息

- 下一步计划
- 1.结合 #118622 问题一起分析
 - 2.进一步解析此票中的日志

#2 - 2023-06-09 17:44 - CD TPM-王祥林
- Status changed from ASSIGNED to NEED_INFO

转到jira上跟踪。

#3 - 2023-06-15 20:56 - CD FW 曹覃刚
- Status changed from NEED_INFO to RESOLVED

转jira跟踪

#4 - 2023-06-15 21:01 - CD FW 曹覃刚
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- Resolution changed from -- to DUPLICATE

#5 - 2023-07-10 16:13 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

7.10
客户验证通过，同步关闭

#6 - 2023-07-10 16:13 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
video(44).mp4	9.4 MB	2023-06-07	CD TEST-方永红
060707(1).tar.gz	3.84 MB	2023-06-07	CD TEST-方永红
060708.tar.gz	7.64 MB	2023-06-07	CD TEST-方永红