

Status:	CLOSED	Start date:	2023-06-07
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-06-08
Test Type:	ST	Root cause:	延迟通知移除不完整。
Description			
【环境信息】：EE环境 【问题出现时间】：20230606 13:15，第204次开机 【前提条件】： 【操作步骤】：1、设置-通知 2、点击“通知历史记录” 【实际结果】 1、通知历史记录下显示“显示近期通知和延后的通知” 2、显示“开启通知历史记录即可查看近期通知和已延后的通知” 【期望结果】 通知延后功能已删除，不应显示通知延后相关信息 【备注】：https://ofs.human-horizons.com/#/download/index/wbFcVkgzRd8%3D 【副屏版本号】：01.00.0106.C104 【中控版本号】：03.02.0088.C103.02_userdebug_2306021732 【VIN】HRYTTESTVINMGM403			

History

#1 - 2023-06-08 14:31 - CD TEST-方永红

- File Snipaste_2023-06-08_14-31-12.png added

#2 - 2023-06-08 15:12 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
205615	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Remove snooze text info in history notification.TC-RID: 1201-0201803IssueID: TS-R-BUG-118626Change-Id: I579ff77cebab9e1abb1d1d4244a801a5e8fea75a			

#3 - 2023-06-08 15:16 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-08
- Root cause set to 延迟通知移除不完整。

■ Current conclusion

已处理，代码已入库。

■ My analysis

延迟通知移除不完整。

■ Next action

测试验证。

#4 - 2023-06-09 15:15 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在 FlatBuild_HH_MCE_FSE.M.D.user.01.00.C104.202306090153 版本验证已通过

#5 - 2023-06-25 13:59 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Snipaste_2023-06-07_19-57-00.png	1.01 MB	2023-06-07	CD TEST-方永红
Snipaste_2023-06-08_14-31-12.png	1020 KB	2023-06-08	CD TEST-方永红