

Figure - Bug #118627
IOVDEV-31105【内部】【VC1】【0100】【台架】【EE环境】【副屏】【设置】副屏在点击设置里的显示亮度时，点击亮度，出现的亮度调节框右下角显示不太合理
2023-06-07 20:43 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-06-07
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0106
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-06-08
Test Type:	ST	Root cause:	需求不明确，之前未处理。
Description			
【环境信息】EE环境 【问题出现时间】：20230527 17：54 【前提条件】：副屏上电；中控、功放已连接；副屏、中控时间一致 【操作步骤】 1.点击设置 2.点击显示 3.点击亮度 【实际结果】 1.显示亮度条，右下角显示自动亮度 【期望结果】 1.亮度条正常显示，右下角无主动亮度四个字 【备注】： 第165次开机 这个亮度条只能手动调节，不需要再显示自动亮度四个字 中控VIN号：HRYTTESTVINMGM817 【中控版本号】：03.02.0082.c101 【副屏版本号】：01.00.0100.c103			

History

#1 - 2023-06-08 15:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
205625	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:SystemUI: Hide auto brightness text when in dialog.TC-RID: 1201-0201903IssueID: TS-R-BUG-118627Change-Id:			

#2 - 2023-06-08 15:14 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-08
- Root cause set to 需求不明确，之前未处理。

■ Current conclusion

已处理，代码已入库。

■ My analysis

需求不明确，之前未处理。

■ Next action

测试验证。

#3 - 2023-06-09 14:51 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

在 FlatBuild_HH_MCE_FSE.M.D.user.01.00.C104.202306090153 版本验证通过

#4 - 2023-06-25 15:22 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED