

|                                |               |                   |                         |
|--------------------------------|---------------|-------------------|-------------------------|
| Status:                        | CLOSED        | Start date:       | 2023-06-08              |
| Priority:                      | Normal        | Due date:         |                         |
| Assignee:                      | CDTS_Test 吴诗雨 | % Done:           | 100%                    |
| Category:                      | CD-FW         | Estimated time:   | 0.00 hour               |
| Target version:                |               |                   |                         |
| Need_Info:                     | --            | Found Version:    | 【中控版本号】：03.02.0088.C103 |
| Resolution:                    | FIXED         | Degrated:         | No                      |
| Severity:                      | Normal        | Verified Version: |                         |
| Reproducibility:               | Every time    | Fixed Version:    | 2023-06-08              |
| Test Type:                     | ST            | Root cause:       | 权限过滤特殊场景遗漏。             |
| Description                    |               |                   |                         |
| 【环境信息】EE环境                     |               |                   |                         |
| 【问题出现时间】：20230608 16：35        |               |                   |                         |
| 【前提条件】：副屏上电，中控已连接              |               |                   |                         |
| 【操作步骤】                         |               |                   |                         |
| 1.查看副屏设置-隐私-权限管理器页面            |               |                   |                         |
| 【实际结果】                         |               |                   |                         |
| 1.设置隐私权限管理器页面多出其他权限选项          |               |                   |                         |
| 【期望结果】                         |               |                   |                         |
| 1.PRD文档没有其他权限选项                |               |                   |                         |
| 【备注】：                          |               |                   |                         |
| 【当前开机次数】：172                   |               |                   |                         |
| 【应用版本】：                        |               |                   |                         |
| 【硬件版本号】：                       |               |                   |                         |
| 【VIN】HRYTTESTVINMGM401         |               |                   |                         |
| 【中控版本号】：03.02.0088.C103        |               |                   |                         |
| 【副屏版本号】：01.00.0106（01.00.0104） |               |                   |                         |

|                                                                                                                                                       |                                             |                                               |                          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------|--------------------------|
| History                                                                                                                                               |                                             |                                               |                          |
| #1 - 2023-06-08 21:11 - IoT scm                                                                                                                       |                                             |                                               |                          |
| Gerrit Merge Information：                                                                                                                             |                                             |                                               |                          |
| ID                                                                                                                                                    | Project                                     | Branch                                        | Uploader                 |
| 205799                                                                                                                                                | general/platform/packages/apps/Settin<br>gs | Pre_figure_turbox-c2130c-la1.1-qssi12<br>-dev | tao.liao@thundersoft.com |
| AF:Settings: Don't show additional permissions entry.TC-RID: 1201-0201808IssueID: TS-R-BUG-118671Change-Id: I6664cc6520d77836c8bc679886ce9f9e4a1e94af |                                             |                                               |                          |

Gerrit Merge Information :

| ID                                                                                                                                                    | Project                                      | Branch                                    | Uploader                 |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------------|--------------------------|
| 205800                                                                                                                                                | general/platform/packages/modules/Permission | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | tao.liao@thundersoft.com |
| AF:Settings: Don't show additional permissions entry.TC-RID: 1201-0201808IssueID: TS-R-BUG-118671Change-Id: Ibfafc365b1875adb9629d9a813351e7ee136817c |                                              |                                           |                          |

#3 - 2023-06-08 21:13 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS\_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-08
- Root cause set to 权限过滤特殊场景遗漏。

■ Current conclusion

已处理，代码已入库。

■ My analysis

权限过滤特殊场景遗漏。

■ Next action

测试验证。

#4 - 2023-06-12 14:38 - CDTS\_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

本地验证通过

#5 - 2023-06-12 16:16 - CDTS\_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

| Files            |        |            |               |
|------------------|--------|------------|---------------|
| IOVDEV-33537.zip | 111 KB | 2023-06-08 | CDTS_Test 吴诗雨 |