

Figure - Bug #118707

【IOVDEV-33694】 【内部】 【VC1】 【0106】 【台架】 【EE环境】 【副屏】 【第三方应用】 哔哩哔哩车机版，小窗模式点击分享，简介，设置无反应

2023-06-09 14:04 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-06-09
Priority:	Normal	Due date:	
Assignee:	CD FW-鲁凯峰	% Done:	0%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:		Found Version:	【副屏版本号】：01.00.0106.C104 【中控版本号】：03.02.0088.C103.02_userdebug_2306021732
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【环境信息】：EE环境			
【问题出现时间】：2023/06/09 13:38 第229次开机			
【前提条件】： 电源on			
【操作步骤】： 1、打开哔哩哔哩车机版 2、小窗模式			
【实际结果】 点击分享，简介，设置无反应			
【期望结果】 点击分享，简介，设置又反应			
【备注】： 【应用版本】： 【硬件版本号】：不涉及 【副屏版本号】：01.00.0106.C104 【中控版本号】：03.02.0088.C103.02_userdebug_2306021732 【中控VIN】HRYTTESTVINMGM403 【第三方应用版本号】哔哩哔哩车机版 2.6.0			
录屏&log: https://ofs.human-horizons.com/#/download/index/LgI%2Bld5zfTY%3D			

History

#1 - 2023-06-09 17:45 - CD FW-鲁凯峰

这个是B站车机版内部View显示的问题,需要B站App去处理,系统侧无法处理

从日志看,Touch事件已经传递给B站的视频播放界面VideoPlayActivity了

//打开视频播放界面

06-06 23:26:03.893 1030 1157 I ActivityTaskManager: Displayed com.bilibili.bilithings/com.bilibili.player.play.ui.playui.VideoPlayActivity: +92m

//点击分享菜单

06-06 23:26:25.479 6239 6239 D ViewTouchDebug: mView : DecorView@76b0a3f[VideoPlayActivity]Receive event : MotionEvent { action=ACTION_DOWN, actionButton=0, id=0, x=531.88916, y=225.99042, toolType=TOOL_TYPE_FINGER, buttonState=0, classification=NONE, metaState=0, flags=0x0, edgeFlags=0x0, pointerCount=1, historySize=0, eventTime=2522634, downTime=2522634, deviceId=-1, source=0x1002, displayId=0, eventId=-14623808 }
06-06 23:26:25.614 6239 6239 D ViewTouchDebug: mView : DecorView@76b0a3f[VideoPlayActivity]Receive event : MotionEvent { action=ACTION_UP, actionButton=0, id=0, x=531.88916, y=225.99042, toolType=TOOL_TYPE_FINGER, buttonState=0, classification=NONE, metaState=0, flags=0x0, edgeFlags=0x0, pointerCount=1, historySize=0, eventTime=2522778, downTime=2522634, deviceId=-1, source=0x1002, displayId=0, eventId=-891353298 }

但是没有响应, 对比全屏和小窗模式的UI View来看,菜单界面是由应用自己通过添加View来实现的,出现问题的时候,View应该还是没有添加成功

#2 - 2023-06-09 18:50 - CD FW-鲁凯峰

- Status changed from New to NEED_INFO

转到在jira上跟踪

#3 - 2023-06-12 15:46 - CDTS_TEST 王成

- Status changed from NEED_INFO to RESOLVED

三方应用自身问题

#4 - 2023-06-12 15:46 - CDTS_TEST 王成

- Status changed from RESOLVED to VERIFIED

#5 - 2023-06-12 15:46 - CDTS_TEST 王成

- Status changed from VERIFIED to CLOSED

Files

哔哩哔哩车机版，小窗模式点击分享，简介，设置无反应.mp4	20 MB	2023-06-09	CDTS_Test 吴诗雨
tlog_iov0201017500006162025411a2212290000000771_000229_0609133748.tar.gz	5.43 MB	2023-06-09	CDTS_Test 吴诗雨