

Status:	CLOSED	Start date:	2023-06-13
Priority:	High	Due date:	
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0110
Resolution:	FIXED	Degrated:	No
Severity:	Critical	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	2023-06-27
Test Type:	ST	Root cause:	中控问题
Description			
【测试版本】 中控0088 副屏0110			
【测试情况】 拔掉网线->然后插上->过程中碰掉了KL15->重新接好->网络图标不同步、音量亮度调节不同步			

History

- #1 - 2023-06-13 18:14 - CD FW-程天颖
- 副屏日志显示，在握手请求后中控未回复，已联系中控开发，进行分析
- #2 - 2023-06-14 14:22 - CD FW-程天颖
- Status changed from New to ASSIGNED
- #3 - 2023-06-24 17:24 - CD FW-廖涛
- Assignee changed from CD FW-程天颖 to CD FW-廖涛
- #4 - 2023-06-27 10:42 - CD FW-廖涛
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-06-27
- Root cause set to 中控问题
- Current conclusion
1. 问题属于偶现问题；
2. 中控开发（汪洋）已经在 0092 版本中处理；
- Next action
- 测试验证；

#5 - 2023-07-03 16:12 - CDTS_TEST 王成
- Assignee changed from CD TEST-方永红 to 移动测试一组_CDTS 刘强

#6 - 2023-07-06 17:14 - 移动测试一组_CDTS 刘强
- Status changed from RESOLVED to VERIFIED

中控：0092
副屏：0116 不复现
副屏：0118 不复现

#7 - 2023-07-06 17:14 - 移动测试一组_CDTS 刘强
- Status changed from VERIFIED to CLOSED

Files			
1441.txt	34.5 MB	2023-06-13	CD TEST-方永红
1455.txt	3.68 MB	2023-06-13	CD TEST-方永红
getprop.txt	50.5 KB	2023-06-13	CD TEST-方永红
Phone-1A2212290000002271 2023-06-13 14-39-52.mp4	3.4 MB	2023-06-13	CD TEST-方永红